



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines



Phone No.: (0651) - 2242889
Fax No. : (0651) - 2242903
E-Mail : ro.ranchi@ibm.gov.in

318/B, Road No-3,
Ashok Nagar, Ranchi,
Jharkhand - 834 002

No. JHK/SKK/Gold-01/RRO/2020

27JHK22001

Date: - 28.10.2021

To,
Shri. Gaurav Agrawal (Nominated Owner),
M/s. Manmohan Minerals Industries Pvt Ltd,
E/75, East Layout, Near Sonari Aerodrum,
Sonari, Jamshedpur, Jharkhand - 831 011

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of Lawa Gold Mine, over an extent of 54.55 hectares situated in Lawa Village, Nimdih Taluk, Saraikela Kharswan District, Jharkhand State - Reg.

Sir,

The following provision of the Mineral Conservation and Development Rules, 2017 was found violated in your above mine during the inspection on **07/10/2021** by the undersigned.

Rule No.	Nature of Violations observed
11(1)	<p>The mining operations in the Lease area were not carried out as per the last approved Modification to the mining plan.</p> <ol style="list-style-type: none">It was proposed in page-65/ Plate 11A of the approved mining plan; for a 148m drive at 226m RL (approx. 88m beyond 740E & 60m above 900N); whereas during inspection no such drive was existing in the Bhalukad Block.It was observed that the roof & side walls of the existing drives were highly disturbed at many places. Huge sludge of debris was found to be accumulated in the drives running down from the raises connected to the old surface workings (in tandem) in the Bhalukad Block. There is no proper access to the adit at 1st level itself.It is proposed in page-84 to provide ventilation in Bhalukad Block upto lower level, whereas during inspection it was observed that the fan was not working and overall the ventilation was found to be very grim at 1st & 2nd level itself.There was no proposal to drive the bypass North x-cut in 2nd level between 680E to 720E whereas such workings were carried out in Bhalukad Block, without any approved modification to the mining plan.It was proposed in page-73 & Plate-11-B to drive 26m raise whereas no such raise was made and approx 240m of drive was made towards east of 400E (between 920N to 940N); which is not as per the existing proposal for 2020-21 for Tamapahar Block and without any approved modification to the mining plan.The entire drives developed again of approx 250m in the Lalkhadan block is not as per the existing proposal for 2020-21 and without any approved modification to the mining plan.It was proposed in page-44 to drill 6 nos of boreholes during 2020-2021, whereas only 3 boreholes has drilled as per the details submitted in Form-I.It was proposed to stope out some areas between 1-B to B-2 & B-2 to 2A levels in the Bhalukad block; whereas proposal for commencing such activity was neither received nor carried out.

मेवित
ISSUED
28/10/21

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under **Rule 62** of MCDR, 2017.
03. The mining operations can be suspended under **Rule 11(2)** if compliance of rule is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (Forty Five) days** from the date of issue of this letter.

Yours faithfully



22/1/24

G.S.Kannan
Senior Mining Geologist

ole

Copy for information to:

1. **The Director (Mines)**, Govt of Jharkhand, 3rd floor, Yojana Bhawan, Jharkhand Mantralaya, Nepal House Area, Doranda, Ranchi – 834 002.
2. **The Controller of Mines (EZ)**, Indian Bureau of Mines, Block-CP, Plot No.13, Salt Lake, Sector-V, Kolkata- 700 091.



22/1/24

G.S.Kannan
Senior Mining Geologist

ole