

## Government of India Ministry of Mines Indian Bureau of Mines Office of the Regoinal Controller of Mines, Jabalpur

File No.MP/Satna/Lst-355 Mine Code: 38MPR35328 Date: 22/10/2019

To,
Shri Bimal Roy (Nominated Owner)
M/s Reliance Ornatus Enterprises & Ventures Pvt Ltd.
502 Plot No 91/94, Prabath Colony
Santacruz (E), Mumbai 400055
Maharashtra

Subject: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to Salaiya Limestone Mine over an extent of 459.566 hect. in Satna District of M.P.

Sir

Undersigned has inspected your mine in the presence of Mines officials Shri Akhilesh Sinh, Shri Sudhakar on 01/10/2019. Following provisions of MCDR 2017 were found violated in your mines at the time of inspection.

## Rule No Nature of violation observed in detail

The Review of Mining Plan for above mentioned mine was approved vide letter No. MP/Satna/Limestone/MPLN/MOD-14/2018-19, dated 22/10/2018 incorporating proposals from 2018-19 to 2020-21. During the inspection it was observed that mining operations in the mine was not carried out in accordance with the proposals given in the approved Review of Mining Plan. The extents of deviation observed during the inspection are as under:

**Rule 11(1)** No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government.

➤ In the approved mod. in mining plan as mentioned above, it was proposed to start back filling from 01.11.2018 in south and north block, fro entire quantitiy of OB generated during the year. As per the injection observation it can be seen that backfilling process is too slow, and it not achieved as per proposal given.

Rule 26 (2) The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1stday of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan.

- ➤ However, yearly report of protective and rehabilitative works carried out during 2018-19, were not submitted to the Regional Controller of Mines, within stipulated time frame and till the date of inspection.
- 2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- 3. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
- 4. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

DEEPAK SHARMA Senior Mining Geologist Indian Bureau of Mines

Copy forwarded for information to:

- 1) The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur.
- 2) The Director, Directorate of Geology and Mining, Khanij Bhawan 29-A Arera Hills Bhopal M.P.