## VIOLATION LETTER



## भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्य्रो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput BHUBANESWAR-751020

Date: 13/11/2018

No.: ORI/IRON/SNG/MCDR-11/BBS/II

सेवा में.

Shri Nirmal Kumar Bathwal, Director,

M/S Penguin Trading & Agencies Limited

Registered Office - Chatterjee International Centre (18th Floor),

Room No 3 & 4, 33A, Jawaharlal Nehru Road, Kolkata-700071

Sub: Violation of provisions of MCDR, 2017 in respect of your Raikela & Tantra Iron Mine over an area of 49.372 Ha in Sundergarh district of Odisha State.

Sir.

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 24.10.2018 by the undersigned along with Shri Dilip Jain, JMG accompanied by S/Shri Rajendra Prasad Khuntiya, Senior Inspector, (Koira Circle), T.D.Behera, Mine Manager, A.K.Sehty, Geologist of your mine.

Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining scheme dated 18/10/2017, i) It is proposed to backfill the area in between section lines F-F' and G-G' by the waste generated from mines during the year 2017-18. ii) It is proposed to construct retaining wall of 130 m in length around waste dump during the year 2017-18.	i) During inspection it is observed that the backfilling was not carried out as proposed in the mining plan and also the waste generated from mines was temporary stacked in the existing working quarry (Tantra) which was not proposed in the mining plan. ii) During inspection it is observed that only 75 m in length retaining wall was constructed during the year 2017-18.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully.

Senior Assistant Controller of Mines

Indian Bureau of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- The Controller of Mines (EZ),भारतीय खान ब्यूरो/Indian Bureau of Mines, Kolkata-700091. 1945 (1)
- डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार /Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग /Heads of Department Building, न्यू कैपिटल /New Capital, भुवनेश्वर /Bhubaneswar-751 001 : For information & further necessary action on following:

Senior Assistant Controller of Mines कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines