VIOLATION LETTER



भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463; TeleFax: 0674-2352490; ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput **BHUBANESWAR-751020**

Date: 14/11/2018

No.: ORI/IRON/KJR/MCDR-81/BBS/ (၅ዓጄ

सेवा में,

Smt. Indrani Patnaik, Mining Lessee, A/6. Commercial Estate, civil town ship Sundargarh Odisha – 769004

Sub: Violation of provisions of MCDR, 2017 in respect of your Unchabali Iron & Mn Mines, over an area of 106.1127 hectare in Keonihar district of Odisha State

Sir.

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 25.10.2018 by the undersigned along with Shri Dilip Jain, JMG accompanied by S/Shri Guru BalaSubramaniam, Mine Manager, Pradeept Mohapatra, Geologist of your mine.

Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining scheme dated	i) During inspection it is observed that
(_)	05/05/2016,	the bench height is more than 10 m
	i) It is proposed to maintain the bench height	and the width of benches are less than
	and width of 10 m & more than 15 m	15 m in the hill top position of the
	respectively in the hill top position of the	quarry.
	quarry.	ii) During inspection it is observed
	1	that waste disposed near to the hill top
	ii) It is proposed to dispose the waste generated	position of the quarry which was not
	from quarry in the designated waste dump area.	proposed in the mining plan.
	iii) It is proposed to rehabilitate an area of 1.19	iii) During inspection it is observed
	ha on worked out benches by afforestation	that rehabilitation on worked out
	during the year 2017-18.	benches is not carried out as proposed.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

Senior Assistant Controller of Mines Indian Bureau of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- 193 9 (1) The Controller of Mines (EZ),भारतीय खान ब्यूरो / Indian Bureau of Mines, Kolkata-700091.
- (2) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार /Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग /Heads of Department Building, न्यू कैपिटल /New Capital, भुवनेश्वर /Bhubaneswar-751 001 : For information & further necessary action on following :

(Ramkishan R)

Senior Assistant Controller of Mines कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines