

भारत सरकार /Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/ Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757
Fax No. : (0832) –2741758
E-Mail : ro.goa@ibm.gov.in
File No:- KNT/BJP/LST-93/Goa

Opp.Old R.T.O.'s Office,
P.O. FATORDA - 403602,
Margao-GOA
Date:- 12.12.2019

MINE CODE:- 38KAR26073

To,

Shri Anil Sood, Nominated Owner
Muddapur Limestone & Dolomite Mine
M/s South west Mining Limited,
JSW Mining Office, Near Tular Cross,
Vidyanagar Post, Torangallu,
Bellary Dist., Karnataka-583275

Sub : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Muddapur Limestone & Dolomite Mine, M/s South west Mining Limited situated in Village – Muddapur, Mudhol - Taluka, Bagalkot- District of Karnataka State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 30/11/2019 by the undersigned in presence of Shri Brajesh Kumar, AGM Mines, Shri Murali Manas P, Mines Manager, Shri Natrajan B, Geologist.

Rule	Nature of Violation observed
11(1)	Mining Operation have not been carried out in accordance with the Modification in Mining Plan approved vide letter no. RMP/Mech-03(KNT)/Goa/2018-19, dated 05.03.2019 to the extent indicated below:- The quantity of top soil as generated while operation to be utilized judiciously for plantation in the earmarked area. However, during inspection it has observed that the top soil materials were used for making safety burm along the mine haul road.
45(7)	As per the Annual return 2018-19, the Ex mine price is furnished as 416.00 Rs/Ton. However, as per the sale value the aforesaid exmine figure is not in order.
46	Notice of appointment in “Form H” for appointment of Geologist in full time basis was not shown during the inspection.

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(S.Prasad)
Deputy Controller of Mines
Indian Bureau of Mines

Copy forwarded to: -

1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
2. The Dy. Director General (Stat), IBM, Nagpur
3. The Director, Directorate Mines and Geology, Govt. of Karnataka 49, Khanij Bhavan, Race Course Road, Bengaluru.

(S.Prasad)
Deputy Controller of Mines
Indian Bureau of Mines