



भारत सरकार/Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/Office of the RCOM, Goa
(आईएसओ-9001:2015)



Phone No.: (0832)-2741757
Fax No. : (0832)-2741758
E-mail : ro.goa@ibm.gov.in

Opp. R.T.O. Office,
P.O. FATORDA – 403 602,
MARGAO - GOA.

NO: KNT/BJP/LST-100/GOA

Mine Code: 38KAR26080

Date: 23/03/20

सेवा में/ To,

Shri Venkatesh Shankara Gowda Patil
M/s Sundara Mineral Industries.
Anand Nagar, Mudhol Taluk.
Bagalkot District.
Karnataka: 587 122

विषय/Subject: Violations of MCDR provisions in respect of Muddapur Limestone and Dolomite Mine, ML No. 2645 of Shri Venkatesh Shankara Gowda Patil, Extent 4.65 Ha., located at Muddapur Village, Mudhol Taluk, Bagalkot District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 02.03.2020 by undersigned in presence of S/Shri V.R. Patil, representative of mine owner; Sridhar Bhat, Qualified Person and other mining officials:

Rules	Nature of Violations observed
11(1)	The mining operation in the lease hold area are not carried out as per the approved Scheme of Mining due to the following reasons: a) Stripping ratio during F.Y. 2018-19 has been proposed to be maintained at 1: 0.16 (tonnage basis) but actually it was maintained at 1:0.05 because waste handling was only 800 tonnes during 2018-19. b) It is proposed to maintain height of working benches at 3m, but during the course of inspection it was found that, at places, height of the working benches were maintained at 4 to 5m.
35(2)	Online self-assessment report of star rating for the F.Y. 2018-19 in the format prescribed by the Indian Bureau of Mines was not found submitted by the lessee as on the date of inspection.
55(1)(3)(iv)	No part-time Mining Engineer and part-time Geologist were found appointed in the mine as on the date of inspection.
45(7)	a) In Annual Return 2018-19 Ex-mine price of BF grade Limestone has been furnished incorrectly as Rs. 300/ tonne. b) Ex-mine price of dolomite is furnished incorrectly.

02. It is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(Krishnendu Chatterjee)
Senior Mining Geologist
Indian Bureau of Mines

Copy for kind information to:

1. The Deputy Director General (Stat.), MMS Division, IBM-Nagpur.
2. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
3. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(Krishnendu Chatterjee)
Senior Mining Geologist
Indian Bureau of Mines