INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

Review and updation of Mining Plan REPORT

Hyderabad regional office

Mine file No : AP/VSK/SPS-7/HYD Mine code: 74APR19014

Name of the Inspecting : M001) S K MUDULI

Officer and ID No.

(ii) Designation : Junior Mining Geologist

(iii) Accompaning mine : Beela Srinivasa Rao-Lessee

Official with

Designation

(iv) Date of Inspection : 09/12/2019

Prev.inspection date :

PART-I : GENERAL INFORMATION

Mine Name : PEDAMADEENA (30.81 HA) (a)

(b) Registration NO.

(C) Category : B Manual (d) Type of Working : Opencast

(e) Postal address

> State : ANDHRA PRADESH District : VISAKHAPATNAM

Village Taluka : Post office Pin Code FAX No. E-mail Phone

Police Station (f)

(q) First opening date : 01/12/2009

(h) Weekly day of rest : SUN

: S/O SURYANARAYANA, KOTA VEEDHI, Address for

correspondance CHODAVARAM,

VISAKHAPATNAM DIST.

Lease Number : APR3501 (a) (b) Lease area : 30.81

: 20 Period of lease (C)

(d) Date of Expiry : 02/12/2029

Mineral worked : TOURMALINE Main 5. Name and Address of the

Lessee : B.SRINIVASA RAO

S/0 SURYANARAYANA, KOTA VEEDHI, CHODAVARAM, VISAKHAPATNAM DIST. VISAKHAPATNAM ANDHRA

PRADESH

Phone:9866632269

FAX :

Owner : B.SRINIVASA RAO

S/O SURYANARAYANA, KOTA VEEDHI, CHODAVARAM, VISAKHAPATNAM DIST. VISAKHAPATNAM ANDHRA

PRADESH

Phone: 9866632269

FAX :

6. Date of approval of Mining Plan/Scheme of Mining

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	No approved proposals exists for the year 2018-19.	No exploratory work was carried out during 2018-19.	the lessee has made 20 nos. trial pits in 2019-20.
1b	Exploration over lease area for geological axis 1 or 2	No approved proposals exists for the year 2018-19	The exploration so far done by means of trial pits is confined to float area which is of G2 scale of exploration and covers over 1.23 Ha and remaining under G3 and G4. In pegmatite body, no exploration has been undertaken for Semi Precious Stone.	
1c	Exploration Agencies and Expenditure in lakh rupees during the year	No approved proposals exists for the year 2018-19	No exploration was carried during 2018-19.	During 2019-20 the exploration has been carried out under the supervision of Qualified person and appointed Geologist.
1d	Balance area to be explored to bring Geological axis in 1 or 2	No approved proposals exists for the year 2018-19	29.58 Ha. balance area was to be explored in G1/G2 level as on date of inspection. (This include 0.01986 Ha of blocked resources)	-
1e	Balance reserve as on 01/04/20	No approved proposals exists for the year 2018-19	0.5652 tonnes-122 category	Reserves has been re-estimated as per MEMC Rules-2015. The RMP has been approved on 21/08/2020.
1f	General remarks of inspecting officers on geology, exploration etc			Lessee has been advised to explore the entire deposit and advised to condcut recovery test of reject. The main SPS are Cats eye and Alenxendrite.
Deve	elopment :			
Sl.No.	Item	Propasals	Actual work	Remarks

2a	Location of development w.r.t.lease area	No approved proposals exists for the year 2018-19	No mining activity carried out in 2018-19.	The mining operations were suspended on 15.5.2013 on account of non submission of Returns and non submission of Scheme of Mining for the block period 2014-15 to 2018-19.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	No approved proposals exists for the year 2018-19.	No mining activity carried out in 2018-19.	
2c	Stripping ratio or ore to OB ratio	No approved proposals exists for the year 2018-19.	No mining activity carried out in 2018-19.	
2d	Quantity of topsoil generation in m3	No approved proposals exists for the year 2018-19.	Nil in 2018-19	
2e	Quantity of overburden generation in m3	No approved proposals exists for the year 2018-19.	Nil in 2018-19	-
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			Except Trial pits, no development has been done as the mine is under suspension w.e.f. 15.5.2013.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	No valid proposals exists for the year 2018-19.	Nil	The mining operations have been suspended on 15.5.2013 on account of non submission of Scheme of Mining and Monthly returns/Annual returns. The last approved document was valid up to 2013-14.

3b	Quantity of ROM mineral production proposed	-do-	Nil	
3c	Recovery of sailable/usable mineral from ROM production	-do-	Nil	
3d	Quantity of mineral reject generation	-do-	Nil	
3e	Grade of mineral rejects generation and threshold value declared.	-do-	NA	
3f	Quantity of sub grade mineral generation.	-do-	Nil	
3g	Grade of sub grade mineral generation	-do-	NA	
3h	Manual / Mechanised method adopted for segregating from ROM	-do-	Nil	
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	-do-	Nil	
3j	Provision of drilling and blasting in mineral benches	-do-	Nil	
3k	Provision of mining machineries in mineral benches	-do-	Nil	
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	-do-	-	-
3m	Total area covered under excavation/pits	-do-	0.7297 Ha	The degraded area so far in the ML area is 0.7297 Ha.

3n	Ore to OB ratio for the pit/mine during the year.	-do-	Nil	
30	Total area put in use under different heads at the end of year	-do-	0.7297 Ha (Old Pit 0.135 Ha-Infra and road 0.01 Ha-Plantation	
3p	Production of ROM mineral during the last five year period as applicable	plan period	No propduction is done in the plan period.	
3q	General remarks of inspecting officers on method of mining etc.			No mining activity except exploration by means of Trial pits is done for the period 2019-20.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	No valid proposals exists for the year 2018-19.	Nil during 2018-19	
4b	Location of topsoil, OB and mineral reject dumps	-do-	No top soil and MR dumps exists in the ML area.	
4c	Number of dumps within lease area and outside of lease area	-do-	Nil	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	-do-	NA	
4e	Number of active and alive dumps.	-do-	NA	
4f	Number of dead dumps.	-do-	Nil	
4g	Number of dumps established.	-do-	Nil	
4h	Whether Retaining wall or garland drain all along dumps are there.	-do-	NA	

PAGE : 7

4i	Length of Retaining wall or garland drain all along dumps	-do-	-do-	
4j	Number of settling ponds	-do-	-do-	
4k	Specific comments of inspecting officer on waste dump management			No dump exists within the leases

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No valid proposals exists for the year 2018-19	Nil	Mineral is yet to be completely mined. Mine working aeas have not yet been matured for back filling.
5b	Area under backfilling of mined out area	-do-	Nil	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	-do-	NA	
5d	Total area fully reclaimed and rehabilitated	-do-	Nil	
5e	General remarks of inspecting officers on backfilling and reclamation etc.	-do-		No part of the ML is completely exhausted of mineral and matured for starting backfilling and reclamation.
	Progressive Mine C	lousre Plan:		
Sl.No.	Item	Propasals	Actual work	Remarks

Sl.No. Item Propasals Actual work Remarks	
---	--

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	To be submitted	Not submitted	Mining operation had been suspended by this office on 15.05.2013.
6b	Area available for rehabilitation (ha) .	No valid proposals exists for the year 2018-19	No part of the mining lease is matured for rehabilitation purpose	-
6c	afforestation done (ha).	-do-	Nil	-
6d	No. of saplings planted during the year	-do-	Nil	-
6f	Any other method of rehabilitation	-do-	None	
6g	Cost incurred on watch and care during the year	-do-	Nil	
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	-do-	Nil	
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	-do-	Nil	
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area	-do-	Nil	-
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	-do-	Nil	

61	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	-do-	Nil	-
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	-do-	Nil	-
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	-do-	Nil	-
60	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	-do-	None	-
6p	Compliance of environmental monitoring (core zone and buffer zone)	-do-	No environmental monitoring carried during 2018-19.	-
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	-do-		The mineral is yet to exhaust and at this stage the progressive closure operations does not arise. Approximatel y 100 nos of plants are there along the boundary.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No approved proposals exists for the year 2018-19.	No despatches are doduring 2018-19.	one
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	-do-	Nil	

7c	Different grade of mineral sorted out at mines.	-do-	Nil	
7d	Any beneficiation process at mines .	-do-	Beneficiation process does not warranted, except washing and manual sorting no other processing is required.	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			The mine is under suspension since 15.05.2013.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	proposals	Nil during 2018-19	-
8b	Concurrent use or storage of topsoil	-do-	-do-	-
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	-do-	NII	-
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	-do-	-	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	-do-	No land in the ML area is matured for restoration, reclamation and rehabilitation.	

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	-do-		100 nos plants exists along the boundary.
8g	Survival rate		The mine is under non operation since May, 2013.	
8h	Water sprinkling on roads to control airborne dust	proposals		
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	No approved proposals exists for improving aesthetic beauty for the year 2014-15 to 2018-19.		The ML area is spread with thorny bushes and shrubs and this adds greenary to the ML area.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Monthly return shall be submitted before the 10th of every month in respect of precesing month and annual return which shall be submitted before the 1st July each year for the proceding financial year.	Submitted the Annual Return for 2018-19.	
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	To be furnished.	No information is furnished. However, during the inspection, the lessee has appointed the Geologist.	

9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	To be furnished.	Submitted as Nil	
9d	Scrutiny of Annual return on afforestation	To be submitted	Submitted as Nil	-
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	To be furnished.	-	-
9f	Scrutiny of Annual return on ROM stock and/or graded ore	To be furnished.	-	-
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost			-
9h	Scrutiny of Annual return on fixed assets	To be furnished.	-	-
9k	Scrutiny of Annual return on mining machineries	To be furnished.	-	-

Details of violat violation pointed	cions observed during curre	nt	inspection	and complia	ance position of	
Violation observed			Show couse position			
Rule NO.	Issued on Compliance	on	Rule NO.	Issue	ed on Compliance on	

Date: (S K MUDULI)

Indian Bureau of Mines