

## मारत सरकार Government of India स्थान मंत्रालय Ministry of Mines

भारतीय चान व्यूनो Indian Bureau of Mines

क्षेत्रीय खान नियमक का कार्यान्य Office of the Regional Controller of Mines





TEL 0135-2676350 / 2671896, E-mail - ro.dehradun@ibm.gov.in

भाईल संख्या File No: HP/SRM/LST-51-DDN

Mine Code: 38HPR10078

दिनाक 20 July 2020

सेवा में То

में, बलबीर सिंह सुपा राम

E-mail: bssr2002@gmail.com

ग्राम व पी- 0 कमरऊ,

तह - 0 पावंटा साहिब.

जिला - सिरमौर, हिमाचल प्रदेश

विषय Sub:

Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Banour Limestone Mine. Mining lease over an area of 0.80 ha located near Village: Banour, Tehsil:

Paonta Sahib, District-Sirmour, Himachal Pradesh State-Reg

महोदय Sir.

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 24.02.2020 in the presence of Shri K.N pant, Mine Manager and the same was communicated to you vide our letter of even number dated on 31-03-2020.

| RULE NO. | NATURE OF VIOLATION OBSERVED   |
|----------|--|
| 11(1)    | Mining operation were not carried out in accordance with the approved Review and Updation of Mining Plan vide letter no 614(2)/MS-B-190/11- DDN dated 18.07.2016 to the following extent:  As per proposal during the year 2019-20, it was proposed to carry out mining operation from 1397 to 1385 mRL by formation of benches 6 mtr height. During the inspection height of benches has been observed up to 10 mtrs whereas as per approved Review and Updation of Mining Plan it should be six meter. |
| 26(2)    | The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before! day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof:  On perusal of office records it is observed that yearly report for the year 2018-19 has not been submitted                                     |
| .72      | to the competent authority by the holder of the lease in the prescribed in this office till date.  |
| 33       | The holder of a mining lease shall, on or before the 30th day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. However, the lessee has not submitted the copies of the plans and sections as per rules.   |
| 55       | Every holder of mining lease shall employ a geologist in the mine. But geologist has not been appointed in the mine.   |

 However, your letter No. Nil dated 27-05-2020 received at this office on 09-06-2020, the reply furnished, was examined and not found satisfactory, as no documents/details has been furnished thus the compliance is not found observed and the violation of Rules 11(1), 26(2), 33 & 55 of MCDR, 2017 still persists.

 In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

Mining Operation can be suspended as per rule 11(2) in case of non compliance of rule 11(1) of MCDR 2017.

5. May initiate appropriate action in accordance with any competent orders/directives etc.

You are therefore directed to show cause within a period of thirty (30) days from the date of issue of this letter, as
to why you should not be prosecuted and / or why mining operation can be suspended under statutory provisions.

Please note that no further notice will be given to you in this regard

Yours faithfully

(दामोदर प्रसादशर्मा 7D P Sharma)

महायक खान नियंत्रक / Assistant Controller of Mines

भारतीय खान ब्यूरों / Indian Bureau of Mines

## प्रतिलिपि सूचनार्थं प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान स्यूरो, उदयपुर। (zo udaspur@ibm gov in)
- 2- निदेशक, उद्योग-निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0), (geologicalwing@gmail.com)
- 3- गार्ड फाइल
- 4- खान फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines