भारत सरकार /Government of India खान मंत्रालय/Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757 Opp.Old R.T.O.'s Office, Fax No. : (0832) -2741758 P.O. FATORDA - 403602,

E-Mail : ro.goa@ibm.gov.in Margao-GOA
File No:- KNT/BJP/Fe-02/GOA-Vol 2 Date:- 16.09.2021

MINE CODE: 30KAR05001

To,

Mr. P. P. Doddanavar, Partner & Nominated Owner M/s Doddanavar Brothers, Corpoarate House, Opp. Hotel Ksema Inn, Near 3rd Railway Gate, Khanapur Road, Belagavi, Karnataka-590016

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Hiremagi, Sulebhavi, Aihole Iron Ore Mines (ML.No. 2649) over an extent of 30.33 Ha. Situated in Sulebhavi&Aihole Villages, Hungund Taluk, and Bagalkot District of Karnataka.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 04/09/2021 by the undersigned in presence of Shri Prakash Y, Mine Manager and mining Engineer & Other Officers.

Rule	Nature of Violation observed
11(1)	Mining operations have not been carried out in accordance with the Review and updatation of Mining Plan(RMP) approved on dated 29/01/2020 to the extent indicated below: (i) It is proposed to be worked by maintaining systematic benches with 6 m height and width of 8 m. However during the inspection it was observed that bench geometry and pit designs for systematic and scientific mining as proposed in the above approved documents were not maintained.
31(4)	Plans and sections are not maintained and uptodated as per this rule.
55(1)(c)(i)	A whole time Geologist is not appointed under this rule.

45(7)	In Annual return 2020-21 :-
	(i) Total quantity of Overburden/waste disposal for the year 2020-21 in
	para 4.2 (C) are not furnished.
	(ii) Registration number as allotted to the buyers in respect of
	sales/dispatch effected from the mine has not been mentioned for all
	the buyers in the Annual Return 2020-21. This violation was already
	been pointed out during the previous inspection of this office; however
	not been rectified so far.

- 02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(S.Prasad)
Dy Controller of Mines & Officer Incharge
Indian Bureau of Mines

Copy forwarded to: -

- 1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
- 2. The Dy.Director General (Stat), IBM, Nagpur
- 3. The Director, Directorate Mines and Geology, Govt.of Karnataka 49, Khanij Bhavan,Race Course Road, Bengaluru.

(S.Prasad)
Dy Controller of Mines & Officer Incharge
Indian Bureau of Mines