

VIOLATION LETTER BY REGISTRATION

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खाननियंत्रक का कार्यालय

सं. ORI/IRON/KJR/MCDR-32/BBS Vol-III / 1796

दूसरी मजिल. महानि काम्लेवरा.
308, डिस्ट्रिक्टसेन्टर, चन्द्रशेखरपुर.
भुवनेश्वर-751 016
दि: 02.09.2015

सेवामें

Shri R R Satpathy, Agent
Joda East Iron Ore Mine
M/s Tata Steel Limited.
At./P.O.-Joda--758034,
Dist.- Keonjhar, Odisha

Sub: Violation of provisions of Mineral Conservation and Development Rules, 1988 ((MCDR, 1988) in respect of Joda East Iron Ore Mine of M/s Tata Steel Ltd., in Keonjhar District of Odisha State.

Sir,

The following provisions of MCDR, 1988 were found violated in respect of your above said mine during inspection on 26 & 27.04.2015 by the undersigned accompanied by Shri Rajesh Kumar, Mines Manager and Dr Rajesh Mukherjee, Geologist of your mine.


Rule No.	Position of Rule	Nature of Violation
27(4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (b) of sub-rule (1) of rule 42, and within twelve months in the case of any other mine.	Surface plan and surface geological plan on 1:5000 scale incorporating details like bench RL, sub-grade stack and waste dump with RL's, ultimate pit limit, retaining wall, check dam etc. under the provision of rule 28 of MCDR 1988 has not been maintained updated.
33(2)	The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods.	Garland drains have not been maintained in the waste dump yard resulting formation of gullies and wash off of dump material degrading low laying area.
33 (5)	Wherever back-filling of waste rock in the area excavated during mining operations is not feasible, the waste dumps shall be suitably terraced and stabilised through vegetation or otherwise.	During inspection of mines it was observed that Waste dump-1 in between ML pillars 22 to 27 has been more than 30 meters height without any terrace and slope of the above waste dump was found to be more than 40 degrees.

Issued
2-9-15

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,



इब्राहिम शरीफ / (IBRAHIM SHARIEF)

सहायक खान नियंत्रक/ Assistant Controller of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- 1) खान नियंत्रक(मध्यंचल)/The Controller of Mines (CZ), भारतीय खान ब्यूरो / Indian Bureau of Mines, नागपुर / Nagpur-440 001.
- 2) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार / Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग / Heads of Department Building, न्यू कैपिटल / New Capital, भुवनेश्वर / Bhubaneswar-751 001



इब्राहिम शरीफ / (IBRAHIM SHARIEF)

सहायक खान नियंत्रक/ Assistant Controller of Mines

कृते क्षेत्रीय खान नियंत्रक/ For Regional Controller of Mines