



भारत सरकार GOVERNMENT OF INDIA  
खान मंत्रालय MINISTRY OF MINES  
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक के कार्यालय  
OFFICE OF THE REGIONAL CONTROLLER OF MINES



रजिस्टर्ड ए डी/सीड पोस्ट  
Phone: 0674-2352463;  
TeleFax: 0674-2352490;  
eMail:  
ro.bhubaneswar@ibm.gov.in  
Plot No. 149, Pokhariput  
BHUBANESWAR-751016  
Date: 11.12.2017

फाईल सं.: ORI/IRON/SNG/MCDR-23/BBS/2263 Mine Code-30ORI13025

सेवा में,

Shri P.R. Goenka, Managing Director  
M/s Korp resources Pvt. Ltd  
161, Rabindra sarani  
P.S-Burra Bazar, Kolkata-700007

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of Tantra Iron ore mine, over an area of 72.560 hectare in Sundergarh District.

Sir,

The following provisions of MCDR, 2017 were found violated in your above mine during inspection on 30/11/2017 by undersigned in presence of Mine officials Shri Chandrasekhar Mishra, Mine Manager, Shri S. Raha, & Shri K.C. Jyotishi, Qualified person.

Rule No.	Nature of violations observed
11(1)	Mining operations have not been carried out in accordance to Scheme of Mining, approved vide this office letter number MS/OTFM/41-ORI/BHU/2012-13 dated 19.04.2013 to the extent given below: 1) Total 50 bore holes were proposed for the plan period 2013-14 to 2017-18 (10 BH per year). However it has been observed during inspection that only 21 bore holes have been drilled. 2) It was proposed to develop the pit in 2016-17 & 2017-18 towards the southern part along the lease boundary. However it has been observed during inspection that the pit has also been developed in northern part along the lease boundary of M/s PTA and M/s JSPL which is against the approved proposal. 3) It is proposed to develop the benches by 6m height and 6m width, whereas it has been observed during inspection that the in south-eastern side along boundary line near pillar "A" bench height has maintained 10-12m. 4) It was proposed to beneficiate the mineral reject generated during mining operation and from dump yearwise. However beneficiation of mineral reject has not been carried out.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully

*Daymond Upadhyay*  
(D. Upadhyay) 11.12.17

ok  
Sr. Assistant Controller of Mines  
Indian Bureau of Mines

Copy forwarded to:

1. The Controller of Mines (EZ/CZ) / Indian Bureau of Mines / Kolkata/Nagpur-440 102.

2. The Director of Mines / Directorate of Mines / Government of Orissa / New Capital / Bhubaneswar-751001.

*Daymond Upadhyay*  
(D. Upadhyay) 11.12.17

ok  
Sr. Assistant Controller of Mines  
Indian Bureau of Mines

1 send  
11-12-17