

**VIOLATION LETTER REGD/ A D**

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय  
[ibmbbsr@dataone.in](mailto:ibmbbsr@dataone.in)



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of Mines.  
Ph-(0674)2742463 / Fax-0674 2744430

File No. ORI/LST/KPT/MCDR-1/BBS / 711

Mahani Complex, 2<sup>nd</sup> Floor  
308, District Centre, Chandrasekharpur  
Bhubaneswar-751 016  
Date : 15.06.2015

To,  
The Managing Director  
IDC OF ODISHA LTD.  
IDCOL House, Ashok Nagar, Unit-II  
Bhubaneswar 751009

Sub: Violation of provisions of MCDR, 1988 in respect of Ampavally Limestone mine (285.429 ha) of M/s IDC OF ODISHA LTD. in Koraput District of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 22.05.2015 by the undersigned and accompanied by Shri J Naga Chandra Mouli, Mines Manager of your mines.

Rule No.	Position of Rule	Nature of Violation
13(1)	Every holder of a mining lease shall carry out mining operations in accordance with the approved mining plan with such conditions-as may have been prescribed under sub-rule (2) of rule 9 <del>or with such modifications, if any, as permitted under rule 10 or the mining plan or scheme approved under rule 11 or 12 as the case may be.</del>	Mining operations are not being carried out in accordance with the approved Mining Plan vide letter no. OTFM/02-ORI/BHU/2013-14 dated 24.01.2014 to the extent indicated below:- <ol style="list-style-type: none"><li>1. Approved exploration with 4(Four) no. of core drill holes with 200 meterage in band no. 42 for the year 2013-14 and 3(Three) no. of core drill holes with 150 meterage in band no. 16 for the year 2014-15 has not been carried out.</li><li>2. As per approved Mining Plan, "Surface run-off water coming out of dump will be allowed to pass through retaining wall, garland drain and settling tank" (refer para 4.4 of PMCP)". Against this no garland drain and settling tank are maintained allowing surface run off</li></ol>

Entered in the  
inspectm register  
23/6/15

15.6.15



		directly discharge in to nala.
33(2)	The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods.	Retaining wall along bottom periphery of waste dump maintained is about 0.7meters height and found filled with waste material. Thus the protective measures carried out along the bottom periphery of waste dump yard is inadequate to prevent wash off there from.
42(1) (c)i	For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules: (c) every holder of a mining lease shall employ, in case of:- (i) category 'A' mines, a whole-time mining engineer and geologist;	A full time Mining Engineer and Geologist have not been employed so far as per provisions of amendment rules.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.

Besides, inability to comply the provision of rule 13(1) is also liable for suspension of mining operations under the provisions of rule 13(2) of MCDR, 1980.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

*Ibrahim Sharief* 15/6/15  
(IBRAHIM SHARIEF)

सहायक खान नियंत्रक/ Assistant Controller of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

(1) खान नियंत्रक(मध्यंचल)/The Controller of Mines (CZ), भारतीय खान ब्यूरो / Indian Bureau of Mines, नागपुर /Nagpur-440 001.

(2) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स /Directorate of Mines, उड़ीसा सरकार /Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग /Heads of Department Building, न्यू कैपिटल /New Capital, भुवनेश्वर /Bhubaneswar-751 001

(IBRAHIM SHARIEF)

सहायक खान नियंत्रक/ Assistant Controller of Mines  
कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines