

खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खाननियंत्रक का कार्यालय

सं. No. ORI/IRON-MN/SNG/MCDR-13/BBS/Vol-III 1494

दूसरी मंजिल, महानि काम्प्लेक्स,
308, डिस्ट्रिक्टसेन्टर, चन्द्रशेखरपुर,
भुवनेश्वर-751 016
दि: 21.05.2015

सेवामें

Shri Pradeep Kumar Saraf,
Director and Nominated Owner
Narayanaposi Iron & Manganese Mine
M/s Aryan Mining & trading Corporation Ltd.
Aryan House, 8th floor,
P-1, Hide Lane,
Kolkata - 700 073

Sub: **Violation of provisions of Mineral Conservation and Development Rules (MCDR), 1988 in respect of Narayanposhi Iron & Manganese Mine of M/s Aryan Mining & Trading Corporation Ltd., in Sundargarh District of Odisha State.**

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 24.04.2015 by the undersigned accompanied by Shri D Patel, Mines Manager and Shri Satish Mohanty, Geologist of your mine.

Rule No.	Position of Rule	Nature of Violation
16(1)	The overburden and waste material obtained during mining operations shall not be allowed to be mixed with non-salable or sub-grade minerals/ores. They shall be dumped and stacked separately on the ground earmarked for the purpose.	It was observed that, waste material found mixed with sub-grade ore/ mineral reject in waste dump-no.1, waste material has not been dumped separately from sub-grade ore/ mineral reject to avoid mixing.
33(2)	The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods.	1. Waste dump in Manganese Quarry-5 area is of about 20 to 23 meters height, slope maintained is more than 33° from horizontal, resulting wash off. 2. Retaining wall along bottom periphery of the waste dump was found filled with dumped material and has not been maintained effectively to prevent wash off of material there from.

in the
near region.

1494
21.5.15

33(6)	The fines, rejects or—tailings from mine, beneficiation or—metallurgical plants shall be deposited and disposed in a specially prepared tailings disposal area such that they are not allowed to flow away and cause land degradation or damage to agricultural field, pollution of surface water bodies and ground water or—cause—floods.	It was observed that, mineral fines generated had been stocked between ML pillars 51/7 to 51/8 over height of about 27 to 30 meters without any terrace, resulting formation of gullies causing wash off of fines there from. Further retaining wall along bottom periphery of the stock yard has not been maintained effectively and found filled with wash out material resulting loss of fines.
-------	--	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

Ibrahim Sharief 21/5/15

इब्राहिम शरीफ / (IBRAHIM SHARIEF)

सहायक खान नियंत्रक/ Assistant Controller of Mines

मूल प्रति पर नहीं / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- 1) खान नियंत्रक(मध्यांचल)/The Controller of Mines (CZ), भारतीय खान ब्यूरो/
Indian Bureau of Mines, नागपुर /Nagpur-440 001.
- 2) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स /Directorate of
Mines, उड़ीसा सरकार /Government of Orissa, हेड्स ऑफ डिपार्टमेंट बिल्डिंग /Heads of Department
Building, न्यू कैपिटल /New Capital, भुवनेश्वर /Bhubaneswar-751 001

Ibrahim Sharief 21/5/15

इब्राहिम शरीफ / (IBRAHIM SHARIEF)

सहायक खान नियंत्रक/ Assistant Controller of Mines

कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines

o/c