



भारत सरकार
Government of India
खान मंत्रालय
Ministry of Mines
भारतीय खान ब्यूरो
Indian Bureau of Mines
Mine Code: 30RAJ06001

पंजीकृत पावती
उल्लंघन पत्र
माखुपुरा औद्योगिक क्षेत्र,
Makhupura Industrial Area
अजमेर.-305 002 (राजस्थान)
Ajmer- 305 002 (Rajasthan)
फैक्स नं 0145.2695202 फोन नं 2695165

संख्या : RAJ/BLW-426/IO-01

दिनांक : 27.09.2018

प्रेषित : Mine Agent
M/s Jindal Saw Ltd.,
Araji No. 9697/6711,
Near Tiranga Hills, Village-Pur,
Tehsil & District-Bhilwara 311 802
Rajasthan

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Dhedwas Iron Ore, Copper & Associate Minerals Mine (Lease area 1556.7817 Ha.) in Bhilwara District of Rajasthan State.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 04.09.2018 by the undersigned in presence of Sh. Dinesh S Patil, Mine Agent:

Rule No.	Nature of violation observed in detail
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Modified Mining Plan (Approved on 18.05.2016) for the year 2017-18: 1) Under future exploration programme, there was proposal to drill 05 bore holes during the year 2017-18, but these proposed bore holes have not been put up till inspection date. 2) During the Year 2017-18 in Tiranga Block Mining was proposed in three pits namely South Central North Pit, Tiranga North Pit and Tiranga North Extension Pit but Mining is going in South Central North Pit only. Further in South Central North Pit ROM production achieved 1.5467 million tonnes against approved proposal of 1 million tonnes and this pit has been extended up to 435mRL whereas approved proposal was up to 460mRL, thereby excess depth of 25m. 3) For whole mine Ore:OB ratio was proposed 1:2.45 whereas actual it is 1:1.76 .It shows that proportionate mine development and production has not been carried out as per proposal in mine. 4) Benches have not been properly developed and maintained in Dulkhera North, Dhulkhera South and Suras Pits as per proposals.
Rule 31(4)	Plans & sections required to be kept under rule 32 have not been maintained up to date within three months.
Rule 45(7)	Part VII of annual return 2017-18 Cost of Production: 1) Zero amount has been shown under item exploration and mining in direct cost. 2) Zero amount has been shown under item royalty and taxes.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

(क) आपकी खदान की सारी संक्रियाएं बंद की जा सकती है।

(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।

03. अतः आपको यह निर्देशित किया जाता है कि आप आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैंतालीस) दिनों के भीतर इस कार्यालय को प्रेषित करें।

(डी. आर. गुर्जर)
सहायक खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 रक्षित पत्रावली।

सहायक खान नियंत्रक
भारतीय खान ब्यूरो