

Violation Letter cum Show Cause
BY SPEED-POST



भारत सरकार/Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/Office of the RCOM, Goa



Phone No.: (0832)-2741757
Fax No. : (0832)-2741758
E-mail : ro.goa@ibm.gov.in

Opp. R.T.O. Office,
P.O. FATORDA – 403 602,
MARGAO - GOA.

NO: KNT/BGM/LST-20/GOA Mine Code: 38KAR02026 Date: 28/09/2021

सेवा में/ To,

Shri R.S.Pujari, (Mine Owner)
M/s Sudha Minerals
Kamkeri Limestone Mine(ML No. 2438)
Taluka: Mudhol, Bagalkot District.
Karnataka: 587 122

Sub: Violations of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Kamkeri Limestone & Dolomite Mine (ML No. 2438), Area 4.12 Ha., located at Kamkeri Village, Mudhol Taluk, Bagalkot District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 01.09.2021 by Shri R.S.Saudagar, Asst. Mining Engineer of this office in presence of Shri Gopal B. Pujari, Lessee representative.

Rules	Nature of Violations observed
11(1)	As per the modification in the Mining Plan (MMP) approved vide letter No. MMP/Man-02(KNT) /Goa/2017-18 dated 20.02.2018, for the period of 2018-19 to 2022-23: It has been proposed to carry out mining operation manually with systematic mining by reducing the existing bench height to 3 meters from bench height prevailing for more than three meters at places but during the course of inspection it was found that height of the working benches were maintained at 5 to 6 metres.
55(1)(c) (ii)	No part-time Mining Engineer and part-time Geologist were found appointed in the mine as on the date of inspection.

02. It is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.
03. In this connection, it is brought to your notice that the above violation were also pointed out by this office during previous inspection and communicated to you vide this office letter of even no. dated 1.01.2021,24.03.2021 and on 28.04.2021.However , the compliance /rectification of violation were not been received so far.
04. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
05. You are advised to rectify the above violations immediately and intimate the position to this office within **30 (Thirty) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(Suresh Prasad)

Deputy Controller of Mines & OIC
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road,Bangalore-560001.

(Suresh Prasad)

Deputy Controller of Mines & OIC
Indian Bureau of Mines