




भारत सरकार/**Government of India**
खान मंत्रालय/**Ministry of Mines**
भारतीय खान ब्यूरो/**Indian Bureau of Mines**
हैदराबाद क्षेत्रीय कार्यालय/**Hyderabad Regional Office**



F. No.AP/VZNR/Mn-124/HYD

603, छठा तल / 603, 6th Floor
सी.जी.ओ.टॉवर्स/CGO Towers,
कवाडीगुड़ा /Kavadiguda,
सिकन्दराबाद/Secunderabad-500 080.

Date: 21/12/2021

To
Sri Ashok Konda, Nominated Owner,
Karlam Manganese ore Mine,
M/s S K Sarawagi & Co,
Sarawagi House,
Kaspa Street, Cheepurupalli-535128,
Vizianagaram District, Andhra Pradesh.

Sub: Violation of provisions of MCDR, 2017 in respect of Karlam Manganese ore Mine over an area of 17.63 ha in Karlam Village, Chipuruopalli Mandal, Vizianagaram district, Andhra Pradesh State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection of the undersigned dated 26.10.2021 of this office accompanied by Sri Asok Konda, Nominated Owner & Sri M.Koteswara Rao, Geologist.

Rule No	Nature of Violations observed
11(1)	The following deviations have been found in the mine from the approved Modification of Mining Plan vide AP/VZNR/MP/Mn-86/HYD Dated 29.9.2020 for the period of F.Y.2020-21 to 2021-22 <u>Exploration:-</u> There was a proposal given in the approved document for drilling i) F.Y. 2020-21, 06 nos, of core boreholes with cumulative depth of 180 mts. and 20 nos. of DTH boreholes with cumulative depth of 1200 mts. ii) F.Y. 2021-22; 08 nos of Core boreholes with cumulative depth of 240 mts. and 32 nos. of DTH boreholes with cumulative depth of 1920 mts. Whereas, during F.Y. 2021-22, 08 nos of Core bore- holes with cumulative depth of 230 mts. have been drilled so far.
26 (2)	A yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting fourth the extent of protective and rehabilitative works carried out has not been submitted for the F.Y.2020-21.

02. In this connection, it is brought to your notice that the above said violations constitute an offence punishable under Rule-62 of MCDR, 2017. Further, inability to comply the provision of Rule 11(1) is liable for suspension of mining operations under Rule 11(2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(P.Guruvaiah)

Junior Mining Geologist

Copy for information:

- 1) खान नियंत्रक महोदय (द), भारतीय खान ब्यूरो, बेंगलूरु.
- 2) The Director of Mines & Geology, Sri Anjaneya Towers, D.No.7-104, B-Block, 5th & 6th Floors, Ibrahimpatnam, Vijayawada, Govt. of Andhra Pradesh-521 456.
- 3) The Assistant Director of Geology & Mining, D.No.2-24-24B, Opp: Naidu Gari Kallam, Thotapalem, Vizianagaram-535003.

का.प्र.

(P.Guruvaiah)

Junior Mining Geologist