



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखंड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – [ro.dehradun@ibm.gov.in](mailto:ro.dehradun@ibm.gov.in)



फाईल संख्या File No: HP/SRM/LST-03

Mine Code: 38HP10012

दिनांक, 12 अप्रैल 2023

सेवा में To: श्री कपिल आनंद एवं श्री गौरव आनंद (लीगन

Email:kapilanand51@gmail.com

उत्तराधिकारी- स्व. श्री केवल कृष्ण आनंद)

खननपट्टाधारक- हियोना चूनापत्थर खान

पता- बाटा मंडी, तहसील-पांवटा साहिब, जिला-

सिरमौर, हि.प्र. 173025

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Hiyona Limestone Mine, Mining Lease over an area of 18.21 ha located near Village-Barwas Tehsil-Paonta Sahib, District-Sirmour in Himachal Pradesh-Reg

महोदय Sir,

उपरोक्त खान का निरीक्षण दिनांक 13.03.2023 को श्री कपिल आनंद, खान मलिक की उपस्थिति में अधोहस्ताक्षरी द्वारा किया गया था एवं निरीक्षण के दौरान खनिज संरक्षण एवं विकास नियमवाली 2017 के निम्न प्रावधानों का उल्लंघन पाया गया।

<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
11(1)	Mining Operation were not carried out in accordance with the approved Review and Updation of Mining Plan with Final Mine Closure Plan (FMCP) vide letter no. 614(2)/MS-B-33/97-DDN dated 09-09-2022 to the following extent: 1. As per proposal on page -21 during the year 2022-23, it was proposed to 300 nos of plantation along the lease boundary and 500 Nos plantations on mine out benches but during the inspection it was observed no such plantation was carried out during the year 2022-23 2. As Per FMCP proposals on page 21, during the year it was proposed to be erect 273 meter fencing in mine at 753608E, 3386881N to 753631E, 3386889N but during the inspection it was observed no such fencing work was not carried out in mine. 3. As per FMCP proposal on page -21 during the year 2022-23, it was proposed to be construct stone wall (260 meter) and garland drain (417 meter) along top of mine out pits but during inspection it was found non such work was carried out in the mine. 4. As per proposals it was proposed development of benches from 1417 mRl to 1369 mRl with six meter height but benches height found more than proposals.
26(1)	According to this rule the holder of a mining lease shall have the responsibility to ensure that the protective measures including reclamation and rehabilitation works have been carried out in accordance with the approved mine closure plan or with such modifications as approved by the competent authority. Whereas during the inspection of mine mentioned herein above and also examination of offices record, Plans and Sections etc, it has been found that the protective, reclamation and rehabilitation measures as envisaged in the approved Progressive Mine Closure Plan (PMCP) and Final Mine Closure Plan(FMCP) have not been carried out by mining leases holder in accordance to the proposals PMCP and FMCP.

2. इस संबंध में, यह आपके संज्ञान में लाया जाता है कि नियम 11(1),26(1)का उल्लंघन नियम 62(1) एमसीडीआर नियम,2017 के तहत दंडनीय अपराध है।

3. इसके अतिरिक्त नियम 11(1) की पालना निर्धारित समयावधि में न होने पर नियम 11(2) के तहत खनन कार्य स्थगन करने की अनुसंशा की जा सकती है,और / या आपके विरुद्ध अभियोग दायर किया जा सकता

समोदर

4. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का तत्काल सुधार कर इसकी सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालीस) दिनों के अंदर इस कार्यालय को भेजे।

भवदीय Yours faithfully,

o/c **दामोदर**  
12.04.2023

(दामोदर प्रसाद शर्मा /D P Sharma)

सहायक खान नियंत्रक /Assistant Controller of Mines  
भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0)।  
(geologicalwing@gmail.com)
- 3- गार्ड फाइल

o/c.

**दामोदर**  
12.04.2023

सहायक खान नियंत्रक /Assistant Controller of Mines