



भारतसरकार / Govt. of India
खानमंत्रालय/Ministry of Mines
भारतीयखानब्यूरो/ Indian Bureau of Mines
हैदराबादक्षेत्रीयकार्यालय/ Hyderabad Regional Office



29555603/29554603

E-mail: ro.hyderabad@ibm.gov.in

No. AP/KNL/Lst-195/HYD

Room No.603, 6th Floor,
CGO Towers, Kavadiguda,
Secunderabad – 500 080.

Date:19.05.2023

To

Sri. N. Sujith Kumar Reddy, Nominated Owner
Racherla Limestone Mine(ML-2)
M/s Rain Cements Limited,
Regd. Office: Rain Center,
34, Srinagar Colony,
Hyderabad-500 073,
Telangana State.

Sub:Violation of provisions of Mineral Conservation and Development Rules,2017 in respect of your Racherla Limestone Mine (ML-2) of M/s.Rain Cements Limited over an extent of 17.82 ha. situated in Racherla Village, Peapully Mandal, Kurnool District, Andhra Pradesh State

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your Racherla Limestone Mine (ML-2) during inspection on 10.05.2023 in the presence of Sri.Srinivas Reddy, Mine Manager, Sri. Suman Reddy, Geologist.

Rule No.	Nature of Violations observed
34A (1)	<p>Every lessee shall carry out a drone survey of the leased area and upto hundred metres outside the lease boundary in the month of April or May every year and submit the processed output [digital elevation model (DEM) and Orthomosaic] images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the Controller General on or before 1st day of July every year.</p> <p>Digital aerial images of the mining lease area have not been submitted as per the Standard Operating Procedure prescribed by Indian Bureau of Mines.</p> <p>The deviations are as follows:</p> <ol style="list-style-type: none">1. Orthomosaic image not submitted in Geotiff format.2. Orthomosaic image & DEM data to be submitted in PCS.3. GCPs are not visible on the orthoimage.4. Resolution of DEM is more than 15cm.5. Error found in GCP data.6. Boundary pillars are not visible over the orthoimage.7. Orthoimage & DEM not submitted for 100 meters buffer zone.8. .shp files for all the allied activities of mining not submitted.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 (1) of MCDR, 2017.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

s/d-
(Madhu Sudhan Yadav. M)
Assistant Controller of Mines

Copy for information:

1. खाननियंत्रक (दक्षिणक्षेत्र), भारतीयखानब्यूरो, बेंगलोर.
2. Director, Department of Mines and Geology, Govt. of Andhra Pradesh.
3. The Assistant Director of Mines & Geology, Kurnool, Kurnool District, Andhra Pradesh.

s/d-
□□□ □□□□ □□□□ .एम(Madhu Sudhan Yadav. M)
I gk; d [ku fu; æd/ Assistant Controller of Mines