

**Violation Letter**  
**Speed Post/Email**



भारत सरकार  
GOVERNMENT OF INDIA

खान मंत्रालय  
MINISTRY OF MINES

भारतीय खान ब्यूरो  
INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक कार्यालय OFFICE OF  
REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, IIस्टेज, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर,  
बेंगलुरु-560022

सं/No. **KNT/BLR/FE/437/BNG** Mine-code:30KAR03156

To,  
Shri B. Rudra Gouda,  
Owner, Haddinapade Iron ore mine  
M/s. BKG Mining Private Limited.  
No. 2198, BKG House,  
K.H.B Colony, Sandur Taluk-583 119  
Ballari District, Karnataka State  
E-mail id- admin@bkggroup.in, bkgsurveygeo@gmail.com, geosurvey@bkggroup.in

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment), 2021 in respect of your Haddinapade Iron ore Mine, ML 2516 of M/s. BKG Mining Private Ltd over an extent of 79.806 ha, in SM Block Village, Sandur Taluk, Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 23.02.2023 by undersigned in presence of Shri P. Sreenivasa Rao, Mine Manager, Shri Naresh Kakumanu, Mining Engineer, Shri Pramod S. Ritti, Geologist, and other mining officials:

Rules	Nature of Violations observed
34A. (1)	The processed output [digital elevation model (DEM) and Orthomosaic] data have not been completely submitted in accordance with the Standard Operating Procedures under sub rule (5) of rule 34A of MCDR, 2017 for carrying out drone survey and submission of Digital Aerial Images of Mining areas. i)The DTM resolution is 28 cm which should be 15 cm or better as per the SOP. ii)The shp files under map of the mining lease area for Waste dump, Afforestation and backfill area have not been prepared correctly. The nomenclature has also not been prepared/maintained as per the approved plan. iii)The soft copy of the output data submission form for the drone survey i.e., Annexure-I with all details have not been submitted.

<b>48</b>	The record of 7 nos. of Exploratory boreholes drilled during year 2021-22 were not found maintained properly with all details in "Form-J" as per provision of this rule.
-----------	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021

03. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Sandeep Kumar Singh)  
Assistant Controller of Mines  
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Sandeep Kumar Singh)  
Assistant Controller of Mines  
Indian Bureau of Mines