INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

FMCP Inspection REPORT

Chennai regional office

Mine file No: TN/CBT/LST-2.MDS Mine code: 38TMN02007

(i) Name of the Inspecting : K08) G.SORNADURAI KANNAN

Officer and ID No.

(ii) Designation : Senior Mining Geologist

(iii) Accompaning mine : Thiru. K.Shankar, QP & Thiru. Vijay, Mines Manager

Official with Designation

(iv) Date of Inspection : 27/05/2023

(v) Prev.inspection date :

PART-I : GENERAL INFORMATION

(a) Mine Name : MADUKKARAI (G.O.725)

(b) Registration NO. : IBM/256/2011

(c) Category : A Mechanised

 $\text{(d)} \qquad \text{Type of Working} \qquad \qquad : \quad \text{Opencast} \\$

(e) Postal address

State : TAMIL NADU
District : COIMBATORE

Village :
Taluka :
Post office :
Pin Code :

FAX No. : 0422-2622286

E-mail : suresh.wandhare@acclimited

Phone : 0422-2622525

(f) Police Station : MADUKARAI
(g) First opening date : 01/01/1934

(h) Weekly day of rest : SUN

2. Address for : M/S A.C.C LTD

correspondance MADUKKARAI CEMENT WORKS,

MADUKKARAI-641105

3. (a) Lease Number : TMN0005 (b) Lease area : 14.29 (c) Period of lease : 10

(d) Date of Expiry : 27/11/1999

4. Mineral worked : LIMESTONE Main

5. Name and Address of the

Lessee ACC LIMITED

> MADUKKARAI CEMENT WORKS MADUKKARAI COIMBATORE

TAMIL NADU Phone: FAX :

Owner Ajay Kapur

> ACC Ltd Madurkkarai Works Coimbatore COIMBATORE TAMIL

NADU Phone: FAX :

Agent : A K SHRIVASTAVA, DIRECTOR

> ACC Ltd., Madukkarai Cement Works, MADUKARAI COIMBATORE

TAMIL NADU

Phone: 0422-2912202 FAX : 0422-2622286

Mining Engineer

VIJAY SRINIVASAN, Full Time

Qualification : B.E MINING Appointment/ 01/09/2018

Termination date

6. Date of approval of Mining : Mining Scheme rule 12 MCDR1988 17/04/2008 04/12/2013 Plan/Scheme of Mining Mining Scheme rule 12 MCDR1988 17/11/2017

MP review under 17(1) MCR 2016

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

| Sl.No. | Item | Proposals | Actual work | Remarks |
|--------|--|---|--|--|
| 1a | Backlog of previous year | No Boreholes has been proposed during 2022-2023. | No Boreholes has drilled | Mine is non- working from 2020- 2021. Lessee has submitted FMCP. |
| 1b | Exploration over lease area for geological axis 1 or 2 | No Additional exploration boreholes was proposed over the lease area during 2022-2023 | No Boreholes has drilled | d Entire lease area is proved upto 130m depth and under G-1 category. |
| 1c | Exploration Agencies and Expenditure in lakh rupees during the year | No Proposal for exploration during 2022- 2023 | No Boreholes has drilled | d So far 33 boreholes have been drilled with 1548 meterage in the lease upto 2022-2023. |
| 1d | Balance area to be explored to bring Geological axis in 1 or 2 | Exploration was not proposed during 2021-2023. | No Boreholes has drilled | area has been explored under G-1 category with 100m X 100m grid interval. 4.35 hectares are nonmineralised area. |
| 1e | Balance reserve as on 01/04/20 | As on 01.04.2023 Proved Mineral Reserves (111) = 1.315 million tons Feasibility Mineral Resources (211) = 3.01 million tons | As on 01.04.2023 Proved Mineral Reserves (111) = 1.91 million tons Feasibility Mineral Resources (211) = 3.01 million tons | The available grade of Limestone in this lease poor quality. The mine is not in operation for 2020-2021 due to uneconomic. |
| 1f | General remarks of inspecting officers on geology, exploration etc | Limestone commonly shows inclusion of pyrite, biotite, muscovite. | The deposit consists of cavity infillings, joints, fractures, | Limestone is whitish and greyish white, coarse to fine grain. |

Development :

| Sl.No. | Item | Propasals | Actual work | Remarks | |
|--------|------|-----------|-------------|---------|--|
|--------|------|-----------|-------------|---------|--|

| 2a | Location of development w.r.t.lease area | During 2022- 2023, working proposal was in R west pit. | Nil | The mine is not in operation from 2020-2021. |
|----|---|---|--|--|
| 2b | Separate benches in topsoil, overburden and minerals (Rule 15) | Minerals - 4 Benches | Nil | The mine is not in operation from 2020-2021. |
| 2c | Stripping ratio or ore to OB ratio | 1 : 1 | Nil | The mine is not in operation from 2020-2021. |
| 2d | Quantity of topsoil generation in m3 | No Proposal during 2022- 2023 | Nil | The mine is not in operation from 2020-2021. |
| 2e | Quantity of overburden generation in m3 | 167000 tons of OB has been proposed during 2022- 2023 | Nil | The mine is not in operation from 2020-2021. |
| 2f | General remarks of inspecting officers on development of pit w.r.t. type of deposit etc | During 2022- 2023, working proposal was in R west pit. | 167000 tons of OB has been proposed during 2022-2023 | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |

Exploitation:

| _ | | | | |
|--------|---|---|-------------|--|
| Sl.No. | Item | Propasals | Actual work | Remarks |
| 3a | Number of pit proposed for production | During 2022- 2023, working proposal was in R west pit. | Nil | The mine is not in operation from 2020-2021. |
| 3b | Quantity of ROM mineral production proposed | The total target of ROM Production proposed was 167000 tons during 2022-2023. | Nil | The mine is not in operation from 2020-2021. |
| 3c | Recovery of sailable/usable mineral from ROM production | 100% Recovery | Nil | The mine is not in operation from 2020-2021. |
| 3d | Quantity of mineral reject generation | No Mineral Rejects has been proposed. | Nil | The mine is not in operation from 2020-2021. |
| 3e | Grade of mineral rejects generation and threshold value declared. | No Mineral Rejects has been proposed. | Nil | The mine is not in operation from 2020-2021. |

| 3f | Quantity of sub grade mineral generation. | No Sub Grade Generation | Nil | The mine is not in operation from 2020-2021. |
|----|--|--|--|--|
| 3g | Grade of sub grade mineral generation | There is No Generation of Subgrade Mineral | Nil | The mine is not in operation from 2020-2021. |
| 3h | Manual / Mechanised method adopted for segregating from ROM | Mechanised method | Nil | The mine is not in operation from 2020-2021. |
| 3i | Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects. | No Beneficiation Study is Proposed | Nil | The mine is not in operation from 2020-2021. |
| 3ј | Provision of drilling and blasting in mineral benches | Drilling & blasting are proposed. | Nil | The mine is not in operation from 2020-2021. |
| 3k | Provision of mining machineries in mineral benches | Excavators Rock Breakers Dumpers | Nil | The mine is not in operation from 2020-2021. |
| 31 | Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM | In 2022-2023, Bench height of 4m was proposed in Mineral. | Nil | The mine is not in operation from 2020-2021. |
| 3m | Total area covered under excavation/pits | 9.72 hect area is proposed for Pit during 2022-2023 | 9.72 hect areas are under Pit only. | Proposal of working is within existing pit, so the mined out area is same. |
| 3n | Ore to OB ratio for the pit/mine during the year. | 1 : 1 | Nil | The mine is not in operation from 2020-2021. |
| 30 | Total area put in use under different heads at the end of year | Land use Pattern as on 01.04.2023. Mines = 9.72 hect Dump = 3.25 hect Green Belt = 0.88 hect | Land use Pattern as on 01.04.2023. Mines = 9.72 hect Dump = 3.25 hect Green Belt = 0.88 hect | The mine is not in operation from 2020-2021. |

| 3р | Production of ROM mineral during the last five year period as applicable | | 2022-2023 = Nil 2021-2022 = Nil 2020-2021 = Nil 2019-2020 = 76792 tons 2018-2019 = 166945 tons | The mine is not in operation from 2020-2021. |
|------------|--|---|--|--|
| 3 d | General remarks of inspecting officers on method of mining etc. | During 2022- 2023, working proposal was in R west pit. | 167000 tons during 2022- | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |

Solid Waste Management - Dumping:

| Sl.No. | Item | Propasals | Actual work | Remarks |
|--------|--|---|--|--|
| 4a | Separate dumping of topsoil, OB and mineral rejects (Rule 32,33) | There is no proposal for dumping during 2022-2023 | Nil | The mine is not in operation from 2020-2021. |
| 4b | Location of topsoil, OB and mineral reject dumps | There is no proposal for dumping during 2022-2023 | Nil | The mine is not in operation from 2020-2021. |
| 4c | Number of dumps within lease area and outside of lease area | Non Lease area | Lease area = 2 Non Lease area = Nil | Dumps are old and existing as per approved plan. |
| 4d | Location of dumps w.r.t. ultimate pit limit (Rule 16) | There is no proposal for dumping during 2022-2023 | Nil | The mine is not in operation from 2020-2021. |
| 4e | Number of active and alive dumps. | - | Nil | The mine is not in operation from 2020-2021. |
| 4f | Number of dead dumps. | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 4g | Number of dumps established. | No Dumps have been established. | Nil | The mine is not in operation from 2020-2021. |
| 4h | Whether Retaining wall or garland drain all along dumps are there. | No Proposal | Nil | The mine is not in operation from 2020-2021. |

| 4i | Length of Retaining wall or garland drain all along dumps | <u> </u> | Nil | The mine is not in operation from 2020-2021. |
|----|--|-----------------------------|---------------------------|---|
| 4j | Number of settling ponds | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 4k | Specific comments of inspecting officer on waste dump management | proposal for dumping during | Lessee has submitted FMCP | The mine is not in operation for 2020-2021 due to uneconomic. |

Solid Waste Management - Backfilling:

| Sl.No. | Item | Propasals | Actual work | Remarks |
|--------|---|--|---|--|
| 5a | Status of part or full extraction of mineral from mined out area before starting backfilling. | Backfilling has proposed on RW Pit during 2022- 2023 | No backfilling has done during 2022-2023 | The mine is not in operation from 2020-2021. |
| 5b | Area under backfilling of mined out area | 1.80 hectares | Nil | The mine is not in operation from 2020-2021. |
| 5c | Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32) | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 5d | Total area fully reclaimed and rehabilitated | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 5e | General remarks of inspecting officers on backfilling and reclamation etc. | 9 | No backfilling has done during 2022-2023 | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |

Progressive Mine Clousre Plan:

| ба | Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2). | It should be on or before 1st July every year. | Submitted for the year 2022-2023. | Submitted within time limit. |
|----|--|--|-----------------------------------|--|
| 6b | Area available for rehabilitation (ha) . | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 6c | afforestation done (ha). | Gap Plantation | Gap Plantation | The mine is not in operation from 2020-2021. |
| 6d | No. of saplings planted during the year | 2500 saplings proposed | No saplings has been planted | The mine is not in operation from 2020-2021. |
| 6e | Cumulative no .of plants | 2500 saplings from 2018-2023 | 200 saplings from 2018- 2023 | The mine is not in operation from 2020-2021. |
| 6f | Any other method of rehabilitation | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 6g | Cost incurred on watch and care during the year | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 6h | Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 6i | Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 6j | Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area | No Proposal | Nil | The mine is not in operation from 2020-2021. |
| 6k | Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir | No Proposal | Nil | The mine is not in operation from 2020-2021. |

| 61 | Compliance on reclamation and rehabilitation by backfilling (v) any other specific means. | No Proposal | Nil | The mine is not in operation from 2020-2021. |
|----|---|---|---|--|
| 6m | Compliance of rehabilitation of waste land within lease (i)afforestation | the safety barrier of | No saplings have been planted within lease area during 2022-2023. | The mine is not in operation from 2020-2021. |
| 6n | Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha) | Gap plantation Proposed in lease area for 2022-2023 | No plantation has been planted. | The mine is not in operation from 2020-2021. |
| 60 | Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation | Green Belt development along 7.5m safety barrier. | No Plantation has been done as per proposal along the safety barrier. | The mine is not in operation from 2020-2021. |
| 6p | Compliance of environmental monitoring (core zone and buffer zone) | Bi-Annually Survey | Nil | The mine is not in operation from 2020-2021. |
| 6q | General remarks of inspecting officers on PMCP compliance and progressive closure operations etc. | 500 saplings proposed along the safety barrier of lease area for 2022-2023 | No Plantation has been done as per proposal along the safety barrier. | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |

Mineral Conservation:

| Sl.No. | Item | Propasals | Actual work | Remarks |
|--------|--|---|-------------|--|
| 7a | ROM Mineral dispatch or grade-wise sorting within lease area | The total target of ROM Production proposed was 167000 tons during 2022-2023. | Nil | The mine is not in operation from 2020-2021. |
| 7b | Method of grade- wise mineral sorting i.e. manual or mechanical. | There is no proposal for grade wise mineral sorting in the lease area. | Nil | The mine is not in operation from 2020-2021. |

| 7c | Different grade of mineral sorted out at mines. | The Limestone of the lease area is Poor quality cement grade | Nil | The mine is not in operation from 2020-2021. |
|----|--|--|--|--|
| 7d | Any beneficiation process at mines . | Crushing & Screening process at outside the lease area | Inside the lease area there is no beneficiation process. | The mine is not in operation from 2020-2021. |
| 7e | General remarks of inspecting officer on Mineral conservation and beneficiation issues | The total target of ROM Production proposed was 167000 tons during 2022- 2023. | The Limestone of the lease area is Poor quality cement grade | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |

Environment:

| Sl.No. | Item | Propasals | Actual work | Remarks |
|--------|---|---|-------------|--|
| 8a | Separate removal and utilization of topsoil (Rule 32) | during 2022- | Nil | The mine is not in operation from 2020-2021. |
| 8b | Concurrent use or storage of topsoil | No Proposal during 2022- 2023 | Nil | The mine is not in operation from 2020-2021. |
| 8c | Separate dumps for overburden, waste rock, rejects and fines (Rule 33) | There is no proposal for dumping during 2022-2023 | Nil | The mine is not in operation from 2020-2021. |
| 8d | Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use | No Proposal during 2022- 2023 | Nil | The mine is not in operation from 2020-2021. |
| 8e | Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc) | No Proposal during 2022- 2023 | Nil | The mine is not in operation from 2020-2021. |

| 8f | Baseline information on existence of plantation and additional plantation done (Rule 41) | | No saplings have planted within lease area during 2022-2023. | The mine is not in operation from 2020-2021. |
|----|---|---------------------------------------|--|---|
| 8g | Survival rate | No Proposal in the document. | Nil | The mine is not in operation from 2020-2021. |
| 8h | Water sprinkling on roads to control airborne dust | • | Nil | The mine is not in operation from 2020-2021. |
| 8i | General remarks of inspecting officer on aesthetic beauty in and around mines area | · · · · · · · · · · · · · · · · · · · | There is no prominent river or stream running in this area. | Outside lease area, small seasonal shallow streams. |

Compliance of Rule 45:

| Sl.No. | Item | Propasals | Actual work | Remarks |
|--------|---|---|--|--|
| 9a | Status of submission of Monthly and Annual returns | MR Submitted up to = May 2023 AR Submitted up to = 2021- 2022 | Returns are submitted within time limit. | Both Annual & Monthly returns are submitted in online |
| 9b | Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager | Annual Return for 2022-2023 is not submitted. | During inspection Mining Engineer is present. | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |
| 9c | Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc. | for 2022-2023 | Nil | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |
| 9d | Scrutiny of Annual return on afforestation | Annual Return for 2022-2023 is not submitted. | Lessee has not planted any saplings after 2020-2021. | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |

| 9e | Scrutiny of Annual return on mineral reject generation (Grade and quantity) | Annual Return for 2022-2023 is not submitted. | Nil | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |
|----|---|--|--|--|
| 9f | Scrutiny of Annual return on ROM stock and/or graded ore | for 2022-2023 | Nil | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |
| 9g | Scrutiny of Annual return on sale value, Ex. Mine price and production cost | | It is captive mine of M/s. ACC | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |
| 9h | Scrutiny of Annual return on fixed assets | Annual Return for 2022-2023 is not submitted. | Nil | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |
| 9k | Scrutiny of Annual return on mining machineries | | Not available in field due to non-working. | The mine is not in operation for 2020-2021 due to uneconomic. Lessee has submitted FMCP. |

PAGE : 13

Details of violations observed during current inspection and compliance position of violation pointed out

| Violation observed | | | Show couse position | | |
|--------------------|-----------|---------------|---------------------|-------------------------|--|
| Rule NO. | Issued on | Compliance on | Rule NO. | Issued on Compliance on | |

Date :

(G.SORNADURAI KANNAN)

Indian Bureau of Mines