



भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो,

क्षेत्रीय खान नियंत्रक कार्यालय, रायपुर

द्वितीय तल, जी० एस० आई० फील्ड प्रशिक्षण केन्द्र, महालेखाकार कार्यालय परिसर,
पोस्ट-विधानसभा, रायपुर-492005 (छत्तीसगढ़)

फोन एवं फैक्स-0771-2282530, 2285590/95 ई-मेल: ro.raipur@ibm.gov.in

उल्लंघन पत्र

रजि. ए.डी./ई-मेल



संघर्ष 2023 INDIA
वैश्विक कुटुम्बकम्
ONE EARTH • ONE FAMILY • ONE FUTURE

सं- CHG/KNK/Fe-30CHG08009

खान कोड- 30CHG08009

दिनांक:- .04.2023

प्रेषित-

श्री अतुल कुमार जैन, निर्देशक,
हहालदी लोह अयस्क खान,
सर्वश्री पुष्प स्टील एवं माइनिंग (प्रा०) लिमिटेड,
751, भूतल, कुण्डेवालान स्ट्रीट, अजमेरी गेट,
दिल्ली-110006
ईमेल-pushpsteels@gmail.com

विषय : छत्तीसगढ़ राज्य के कांकेर जिले में स्थित आपके हहालदी लोह अयस्क खान 66.00 हेक्टर में खनिज संरक्षण एवं विकास नियमावली 2017 एवं 2021 के नियमों के संबंध में।

महोदय,

आपकी उपरोक्त खान का निरीक्षण दिनांक 16.02.2023 को अधोहस्ताक्षरी द्वारा आपके प्रतिनिधि श्री सरयू तिवारी, की उपस्थिति में किया गया तथा खान के निरीक्षण के उपरांत पाया गया कि आपने खनिज संरक्षण विकास नियमावली 2017 एवं संशोधित नियमावली 2021 के निम्नलिखित नियमों का उल्लंघन किया है।

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
11(1)	<p>The Mining operations required to be carried out in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines. However, Mining operations observed not carried out in accordance with the Review & updation of Mining Plan (RMP) approved dated: 20.05.2021 to the extent indicated below:-</p> <ol style="list-style-type: none">Exploration was proposed to be carried out by drilling of 47 nos. of core boreholes in FY 2021-22 & 2022-23. However, exploration as proposed has not been carried out so far.In year 2021-22 & 2022-23, temporary fines dump/stack of 05 m height was proposed at earmarked place between grid line 2242166 to 2242385. However, it is observed during inspection that, temporary fines dump has been made confined to grid line 2242350 to 2242500 by increasing its height of about 10 to 15 mt. Further, this fines dump/stack has not been found terraced at 3 -5 m interval along height as envisaged. Moreover, no any environmental protection measures (retaining wall, garland drain, sieved culvert, siltation tank etc.) observed constructed around the said fines dump as envisaged in approved RMP. (Refer text and plate no. 08 of RMP) <p>Hence, above are observed to be against the systematic & scientific development of mines and also against the protection of environment in the mine.</p>
26(2)	<p>A yearly report setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, ought to be submitted before the 1st day of July each year for the preceding financial year, has not been submitted so far for the year 2021-22.</p>
31(4)	<p>The Plans & sections have not been maintained up to date within three months as required under this for Category 'A' mines; as Updated Plans & sections have not made available during the inspection.</p>
35(2)	<p>Every holder of a mining lease shall monitor his mining and allied activities as per the template of star rating in the format specified in this behalf by the Indian Bureau of Mines from time to time, and shall submit online its self-assessment report before the 1st day of July every year for the previous financial year. However, it is observed that you have not submitted the self-</p>

	assessment report for the above referred mine within the prescribed date as specified in this Rule. Details of delay in submission of template of star rating by you are enumerated as below:				
	Year	Due date of Submission	Date of Submission	Delay period in days	
	2021-22	30/06/2022	28/08/2022	59 Days	
45 (5) (C)	The holder of a mining lease shall submit online returns in respect of each mine to the Regional Controller and the authorized officer of the Indian Bureau of Mines in the following manner namely:- An annual return which shall be submitted before the 1 st day of July each year for the preceding financial year in electronic form, along with a signed print copy of the same. Details of delay in submission of annual return by you are enumerated as below:				
	Year	Due date of Submission	Date of Submission	Delay period in days	Amount to be paid in Rs.
	2021-22	30/06/2022	02/07/2022	2 Days	20,000/-
	In this respect violation cum show cause notice was also issued earlier vide this office letter of even no. dated 10.10.2022, in spite of that compliance has not been reported from your end so far.				
55	Full time Mining Engineer and Geologist have not been appointed as required under this rule.				

02. It is brought to your notice that non-compliance of Rule 35(2) of MCDR, 2017, attracts provisions of Rule 35(4A) & (4B) of MCDR, 2017 under which:

(i) The mining operations may be suspended.

(ii) The holder of mining lease shall be liable to pay an amount of ten thousand rupees per day for such delay to the authorised officer of the Indian Bureau of Mines in case of non-filling/delay in filling of template of Star Rating.

03. Further, action according to Rule 45(7) of MCDR, 2017 can be initiated, if compliance of Rule 45 is not found satisfactory.

04. You are therefore directed to deposit the amount for aforesaid delay in submissions at the earliest through Bharatkosh Portal (<https://bharatkosh.gov.in>).

05. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 एवं संशोधित नियमावली 2021 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का अनुपालन नहीं होने पर आपके विरुद्ध अभियोग याचिका दायर किया जा सकता है एवं खनिज संरक्षण एवं विकास नियमावली 2017 एवं संशोधित नियमावली 2021 के नियम 11(2) एवं 45(7) के अंतर्गत खान की समस्त खनन सक्रियाएं बंद की जा सकती है।

06. अतः आपको सलाह दी जाती है कि आप उपरोक्त नियमों का उल्लंघन का अतिशीघ्र सुधार करें एवं इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय,

(प्रेम प्रकाश)
क्षेत्रीय खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि: सूचनार्थ एवं आवश्यक कार्यवाही हेतु :- (ईमेल द्वारा)

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर-440001 ।

2. संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ़ इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, अटल नगर, छत्तीसगढ़।

क्षेत्रीय खान नियंत्रक
भारतीय खान ब्यूरो