

GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES OFFICE OF THE REGIONAL CONTROLLER OF MINES



File No.: MP/JBP/Iron ore-17

Jabalpur, Dated: 05/04/2023

To,

M/s RMG Super Mines Pvt.Ltd 33, Jagran Bhawan, Press Complex M.P Nagar, Bhopal (M.P)-462011

Email-rmgsupermines@hotmail.com ,sharma.nitin074@gmail.com

Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to Dhamda Iron Ore Mine, Mine Code 30MPR18019 over an extent of 4.54 ha in Jabalpur District of M.P.

Sir,

The following provision of Mineral Conservation and Development Rules 2017 were found violated in your above mentioned mine during the inspection by the undersigned on 27/03/2023 in presence of QP Shri Indraneel Dhawande and Mining Engineer Shri. Punith Kumar Dhruv.

Rule No	Nature of violation observed in detail
Rule 11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.
	1. Pit extended beyond the Mining Lease Boundary in between the boundary pillars BP 2A and 3.
	2. Working Pit has encroached the 7.5m Safety barrier between BP 2A and BP 03.
	3. Bench parameters are not maintained as proposed, high walls are created towards BP04 to BP 06 and BP 2A to BP 03.
	4. The excavated top lateritic soil is found Dumped outside the Mining leas boundary between BP 04 and BP 06.
	5. Working found in the South-Western part of the lease covered b Boundary pillars BP-2B, BP-03, BP-04, BP-05, BP-06 and BP-07 wherea proposal given for the other part of the lease.
Rule 31(4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine
	The updated plans and sections are not matching with actual field conditions.

Rule 34A

Every lessee shall carry out a drone survey of his leased area and up to hundred meters outside the lease boundary within six months before submission of any mining plan document or modification thereto to the Indian Bureau of Mines for approval and shall submit processed output [digital elevation model (DEM) and Orthomosaic images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the concerned Regional Controller of Mines and the Controller General along with the application for approval or modification of mining plan.

The required Drone survey data has not been submitted as per the Standard Operating Procedure for carrying out Drone Survey and submission of digital images issued by Indian Bureau of Mines.

- 2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- 3. Non compliance of rule 11(1) of MCDR, 2017 may lead to suspension of mining operation under the provision of rule 11(2) of MCDR-2017.
- 4. You are advised to rectify the above violations immediately and intimate the position to this office within a period of 45 days from the date of issue of this letter.

Yours faithfully

(Kathroju Naveen)
Sr. Asst. Controller of Mines,
Jabalpur Region, IBM

Copy to:

1. The Director of Geology & Mining, Government of Madhya Pradesh, Khanij Bhavan, Area Hills, Bhopal (MP). (Dump Extended outside of the Mining Lease granted).

2. The District Collector, Jabalpur

(Kathroju Naveen)
Sr.Asst. Controller of Mines,
Jabalpur Region,
IBM

1. खान नियंत्रक, भारतीय खान ब्यूरो,नागपुर को सोचानार्थ प्रेषित

(कथोरोजू नावीन) वारिसता सहायक खान नियंत्रक