

Violation

भारत सरकार/ **GOVERNMENT OF INDIA**
 खान मंत्रालय/ **MINISTRY OF MINES**
 भारतीय खान ब्यूरो/ **INDIAN BUREAU OF MINES**
 क्षेत्रीय खान नियंत्रक कार्यालय /
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
 दूरभाष: 080-23371027 / 23375366/67
 Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, IIस्टेज, तुमकुररोड,
 गोरुगुंटापाल्या, येशवंतपुर,
 बेंगलुरु -560022

सं./No.MCDR-MiFLOFE/11/2022-BNG-IBM_RO_BNG

दिनांक/Date: 10/08/2023

सेवामें/ To,

Smt. Sindhu Srinivasalu, Nominated Owner,
 M/s. Garudadhri Impex Private Limited,
 No 464, Ward No. 15/27, 1st Floor,
 Dam Road, Hospet,
 Ballari -583 201.
E-mail: giplmines@gmail.com

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **K. K. Kaval Iron Ore Mine (ML No. 2583)** over an extent of 20.64 Ha having Mine code **30KAR07032** in Kudurekanive Kaval village, Hosdurga Taluk, Chitradurga District, Karnataka state.

महोदया/ Madam,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 in your above mine during inspection on 24.07.2023 by Shri. Gangadhar Bhakat, AME in the presence of Sri. Basavaraj R, Mines Manager and other mine officials.

Rule	Nature of violations observed
11(1)	<p>The Mining operations are required to be carried out in accordance with the approved Review and Updation Mining Plan document vide letter no. 279/903/2006/BNG dated 26/04/2019, for the period 2019-20 to 2022-2023. However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <ol style="list-style-type: none"> For the Year 2022-23, it was proposed to generate 9189 tonnes of waste removal (Development). However, a total of 2,90,000 Tons waste has been generated during the year 2022-23. The deviation is observed more than 30 times of proposed quantity of the waste. As per the proposal for the year 2022--23 the bench geometry to be maintained 7m of bench height & 9m of bench width. However, it was observed during the inspection the benches of pit 1 at the section lines

	A-A' & B-B' are not maintained as per the proposal. iii. Waste dumping has not been carried out earmarked proposed location.
26(2)	A yearly PMCP report as per the format specified by the Indian Bureau of Mines has not been submitted before 1st July 2023 setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved progressive mine closure plan.
33	Updated Surface plan, Geological Plans and Sections as per the Rule 32 of MCDR, 2017 are not submitted on or before 30th June 2023 for the year 2022-23.
46	The notice of appointment of Geologist under rule 55 of MCDR, 2017 has not been submitted at this office.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The mining operation can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(डा.सुधाकरटी.एल./Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी /Senior Mining Geologist
भारतीयखानब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ /Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, MMS Division, Indian Bureau of Mines, Nagpur.
3. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001.

वरिष्ठ खनन भूविज्ञानी /Senior Mining Geologist
भारतीयखानब्यूरो/Indian Bureau of Mines