MCDR INSPECTION REPORT

	O GENERAL	
SN	Particulars	Details
1(a)	Name of the Mine	Roghada Limestone Mines, Sy/No.46/2P&46/4/1P, Area-4.0Ha
1(b)	Name of Inspecting officer	Sh. G.Ram, DCOM
1(c)	Date of Inspection & Type	11/4/2022 AN & RMP
1(d)	Accompanying officer	Sh. Nagha Bhai Vanda, Sh. Harsh Trivedi, Technical Person.
2	Total Lease Area (Ha) with breakup of Non-	ML Area: 4.0ha
	forest and forest land	Survey Nos.: 46/2P&46/4/1P
3	Mine code	38GUJ21101
4	IBM Registration Number under rule 45 of	IBM/17858/2014
	MCDR, 2017	
5	Name of the lessee, Address, phone, email and	Shri Merkhi Bhai Jetabhai Vanda, Lessee, At & PO-Roghada,
	fax number	Taluka-Kutiyana, District-Porbandar, Gujarat State
6	Village	Roghada
7	Taluka/Mandal	Kutiyana
8	District	Porbandar
9	Pin code	362245
10	State	Gujarat
11	Post office	Kutiyana
12	Nearest police station	Kutiyana
13	Nearest Railway station	Ranavav
14	Date of Grant of Mining Lease	06.2.2013
15	Date of Execution	06.2.2013 (Expiry-05.2.2063 As per MMDR Act 2015)
16	Date of opening of Mine	08.8.2013
17	Date of first Renewal, if applicable and its expiry	Not Applicable
18	Date of second Renewal, if applicable and its	Not Applicable
	period & expiry	
19	Date of submission of renewal application if	Not Applicable, since ML is executed in 2013 only.
	Mining Operations are continuing under deemed	
20	Name of the Nominated Owner with Address,	Shri Merkhi Bhai Jetabhai Vanda, Lessee, At & PO-Roghada,
	phone, email, fax and date of appointment	Taluka-Kutiyana, District-Porbandar, Gujarat State
21	Name of the Mine Agent with Address, phone,	Shri Merkhi Bhai Jetabhai Vanda, Lessee, At & PO-Roghada,
	email, fax number and date of appointment	Taluka-Kutiyana, District-Porbandar, Gujarat State
22	Name of the Mines Manager with Address,	Not Appointed
	phone, email, fax number and date of	
	appointment in mines	
23	Name of the Mining Engineer, Qualification and	Not Appointed-Mine workings discontinued wef 01.11.2021 due
	total experience with Address, phone, email, fax	to NGT /State. (Discontinued Notice is not submitted), Violation
	number and date of appointment in mine	pointed out.
24	Whether Geologist and Mining Engineer	Not Appointed-Mine workings discontinued wef 01.11.2021 due
	appointed in mines satisfy the rule & carrying out	to NGT /State. (Discontinued Notice is not submitted), Violation
	their duties as per rule.	pointed out.
25	Date of Approval of Mining Plan/Modified	682(23)(MP)(802)/2012-MCCM(N)/UDP Dated 04.9.2012 for
	Mining Plan with five-year period and specific	2013-14 to 2017-18, 684(4)(1)(MP-132)/2018-MCCM(N)/UDP
	condition in approval letter, if any.	Dated 13.6.2018 for 2018-19 to 2021-22
26	Date of Approval of Scheme of Mining/Modified	MMP-684(4)(1)(MP-285(132)/2020-21-GNR Dated 05.11.2020
	Scheme of Mining with five-year period and	for 2020-21 to 2021-22 ,684(4)(1)(MP-419)/2022-GNR Dated
	specific condition in approval letter, if any.	27.5.2022 for 2022-23 to 2026-27
27	Mineral(s) granted in lease and proved for mining	Limestone
28	Method of Mining(Opencast, Underground)	Opencast Mining
29	Category (Fully Mechanised, Others or Manual)	A-Category
30	Captive/Non Captive	Non-Captive

Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. -

1	0 Exploration			
SN	Item	Proposals (2021-22)	Actual work	Remarks
1a	Backlog of previous year	No backlog		
1b	Exploration over lease area for G-axis 1 or 2.	08 Number of exploratory core bore holes/209.52m has been		
1c	Exploration Agency & Exp. in lakh Rs during year	drilled in entire mining lease area is G1/G2 level. (Dec,18 to		
1d	Balance area to be explored to bring G-axis in 1or2	Jan,19) & Expenditure-7,55,790	0/-Rs.	
1e	Balance reserves (Million Tonnes) as on 01.04.22	Total resources-2.083million	tonne, out of	this Reserves
		(111,121&122) 1.098million Te	onne.	
1f	General remarks of inspecting officer on geology,	Lessee has been carried out 08	8no of core boreho	oles. No further
	exploration etc.	exploration is required.		

SN	.0 Development Item	Proposals (2021-22)	Actual work	Remarks
2a	Location of development w.r.t. lease area	Proposed as earmarked in plate3B	Not done,	Presently
2b	Separate benches in topsoil, OB and mineral	Proposed for separate removal	NIL	mine is not
2c	Stripping ratio or ore to OB ratio	Not Proposed	1,122	working due
2d	Quantity of topsoil generation in m3	597m3		to EC/NGT
2e	Quantity of overburden generation in m3	Not Proposed		
2f	General remarks of inspecting officer on	The lease area is developed by min	e pit. Presently mir	e is not workin
	development of pit w.r.t. type of deposit etc.	due to EC/NGT	e pro resently nu	
3	0 Exploitation			
SN	Item	Proposals (2021-22)	Actual work	Remarks
3a	Number of pits proposed for production	Pit No.1 as earmarked	Not done,	Presently
3b	Quantity of ROM production proposed	194422T	OT	mine is not
3c	Recovery of saleable/usable mineral from ROM	100%		working due
3d	Quantity of mineral reject generation	Not proposed		to EC/NGT.
3e	Grade of mineral reject and THV declared	34%Cao	-	
3f	Quantity of sub-grade mineral generation	Not Proposed	-	
3g	Grade of sub-grade mineral generation	Not Proposed		
3h	Manual / Mech. method adopted for	Mechanised		
	segregating			
3i	Any analysis or beneficiation study proposed &	Not Proposed		
	carried out for sub-grade mineral and reject			
3ј	Provision of drilling & blasting	Not proposed	-	
3k	Provision of machineries in mineral benches	Excavator (0.9M3)/ JCB	_	
31	Whether height of benches in overburden and mineral	No OB benches.		
2	suitable for method of mining proposed in MP/SOM		NII	_
<u>3m</u>	Total area covered under excavation/pits	0.2902Ha area in plan period	NIL NIL	_
<u>3n</u>	Ore to OB ratio for the pit/mine during the year	1:0.0		Total Pit area i
30	Total area put in use under different heads	0.2902Ha area proposed, plan period	NIL	about-2.0351H
3p	Production of ROM mineral during last five-	2018-19- 39999T	121434T	
СP	year period, as applicable	2019-20- 50210T	49800T	
	yeur period, us appriedore	2020-21- 148969T	79681T	
		2021-22-194422T	OT	
		2022-23-194422T	0T(Till date)	
3q	General remarks of inspecting officer on	Presently mine is not working du		posed method of
- 1	method of mining etc.	mining is mech. O/c method with		
4	.0 Solid Waste Management-Dumping			
SN	Item	Proposals (2021-22)	Actual work	Remarks
4a	Separate dumping of topsoil, OB & reject	Topsoil-597Tm3	0T	
4b	Location of topsoil, OB & mineral reject dumps			
4c	Number of dumps within & outside lease area	Not proposed	NIL	
4d	Location of dumps w.r.t. ultimate pit limit			
4e	Number of active & alive dumps	Not proposed	NIL	
4f	Number of dead dumps			
4g	Number of dumps stabilised	1		
4h	Whether Retaining wall or garland drain	1		
4i	Length of Retaining wall or garland drain	1		
4j	Number of settling ponds	Not requires & propose.	NIL	1
4k	Specific comments of inspecting officer	NIL	1111	I
	.0 Solid Waste Management-Backfilling	NIL		
		Proposals (2021-22)	A atual work	Domontra
SN 5a	Item Status on part or full extraction of mineral from	Proposals (2021-22) Not Proposed	Actual work Not done	Remarks
Ja	mined out area before starting backfilling	not rioposed	not dolle	
5b	Area under backfilling of mined out area	-1		
50 5c		-1		
50	Concurrent use of topsoil for restoration or rehabilitation of mined out area			
54	Total area fully reclaimed & rehabilitated	-1		
5d 5e	General remarks of inspecting officer on backfilling,	There are no OB/Waste gene	ration Hance no	hackfilling
50	reclamation etc.	reclamation proposed & not carrie		o backinning o
		1 rectamation proposed & not carrie	a out.	
6	.0 Progressive Mine Closure Plan			
0	w i rogrossive mille Closure i fall			1 .
J	Item	Proposals (2021-22)	Actual work	Remarks

SN Item Proposals (2021-22) Actual work Remarks	SN Item	Proposals (2021-22)	Actual work	Remarks
---	---------	---------------------	-------------	---------

6a	Whether Annual report on PMCP submitted on time and correctly .26(2)	Proposed	Not Submitted	VL under rule 26(2) pointed
бb	Management of worked/mined out benches i) Area available for rehabilitation (ha) ii) Afforestation done (ha) iii) No. of saplings planted during the year iv) Cumulative no. of plants v) Any other specific method of rehabilitation vi) Cost incurred on watch & care during the year	Not proposed	Not done	out.
6с	Compliance on reclamation and rehabilitation by backfilling i) Voids available for backfilling (L X B X D) ii) Void filled by waste/tailings iii) Afforestation on the backfilled area iv) Rehabilitation by making water reservoir v) Any other specific means	Not proposed	Not done	
6d	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	Within 7.5m barrier 200No./0.1Ha	100No. (Survival less)	
6e	Compliance of Environmental monitoring (core zone & buffer zone)	periodic monitoring of air borne dust, water, noise etc.	done by third party agency	
6f	General remarks of inspecting officer on PMCP compliance & progressive	Annual report on PMCP is provision of rule 26(2) pointed of	not submitted. ` ut.	Violation under
	<u>0 Mineral Conservation</u>			
SN	Item	Proposals (2021-22)	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	194422T	0T	
7b	Method of grade-wise mineral sorting i.e. manual or mechanical	Manual & Machines	NIL	
7c	Different grade of mineral sorted out at mines	Chemical/Cement grade	NIL	
7d	Any beneficiation process at mines	Not proposed	NIL	
7e	General remarks of inspecting officer on Mineral conservation & beneficiation issues	There is no mineral rejects/su ROM is utilised by proper sizing & s	ograde generated sorting, blending	presently. Entire
8.	0 Environment			
SN	Item	Proposals (2021-22)	Actual work	Remarks
8a	Separate removal and utilization of topsoil	removing separately	Not done	ML area is
8b	Concurrent use or storage of topsoil	Not proposed		devoid of
8c	Separate dumps for OB, waste, rejects and fines			OB/Waste
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not proposed		
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations	Not proposed		
8f	Baseline information on existence of plantation	Not proposed		
8g	Survival rate	75-80%		
8h	Water sprinkling on roads to control airborne dust	Proposal for supress dust		
8i	General remarks of inspecting officer on aesthetic	The aesthetic beauty of area is m		plantation done
	Destrict in and around mines are			
•	beauty in and around mines are	in 7.5m but surrounding area is l	ess intigated faild	
	0 Compliance of Rule 45			
	0 Compliance of Rule 45 Item	COMMENTS F	emarks	
9. S.N. S.N.	0 Compliance of Rule 45	COMMENTS F Online return Submitted up to till da Details GIVEN in A.R.2021-22 is su	Remarks te –	Remarks
S.N.	0 Compliance of Rule 45 Item Status of submission of Online Monthly/ Annual returns Item Scrutiny of Annual return for information on Mining	COMMENTS F Online return Submitted up to till da	Remarks te – bmitted on 10.5.21 Details as	Remarks
S.N. S.N. 9b	0 Compliance of Rule 45 Item Status of submission of Online Monthly/ Annual returns Item Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager Scrutiny of Annual return on land use pattern for	COMMENTS F Online return Submitted up to till da Details GIVEN in A.R.2021-22 is su /Monthly return	Remarks te – bmitted on 10.5.21	
S.N. S.N. 9b 9c	0 Compliance of Rule 45 Item Status of submission of Online Monthly/ Annual returns Item Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	COMMENTS F Online return Submitted up to till da Details GIVEN in A.R.2021-22 is su /Monthly return	Remarks te – bmitted on 10.5.21 Details as per given in	
S.N. S.N. 9b 9c 9d	0 Compliance of Rule 45 Item Status of submission of Online Monthly/ Annual returns Item Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc. Scrutiny of Annual return on afforestation	COMMENTS F Online return Submitted up to till da Details GIVEN in A.R.2021-22 is su /Monthly return	Remarks te – bmitted on 10.5.21 Details as per given in	
S.N. S.N. 9b 9c	0 Compliance of Rule 45 Item Status of submission of Online Monthly/ Annual returns Item Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc. Scrutiny of Annual return on afforestation Scrutiny of Annual return on mineral reject generation	COMMENTS F Online return Submitted up to till da Details GIVEN in A.R.2021-22 is su /Monthly return	Remarks te – bmitted on 10.5.21 Details as per given in	
S.N. S.N. 9b 9c 9d 9e	0 Compliance of Rule 45 Item Status of submission of Online Monthly/ Annual returns Item Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc. Scrutiny of Annual return on afforestation	COMMENTS F Online return Submitted up to till da Details GIVEN in A.R.2021-22 is su /Monthly return	Remarks te – bmitted on 10.5.21 Details as per given in	
S.N. S.N. 9b 9c 9d 9e 9f	0 Compliance of Rule 45 Item Status of submission of Online Monthly/ Annual returns Item Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc. Scrutiny of Annual return on afforestation Scrutiny of Annual return on mineral reject generation Scrutiny of Annual return on ROM stock/ graded ore Scrutiny of Annual return on sale value, Ex. Mine price	COMMENTS F Online return Submitted up to till da Details GIVEN in A.R.2021-22 is su /Monthly return	Remarks te – bmitted on 10.5.21 Details as per given in	

10- Details of violations observed during current inspection and compliance position of earlier violation pointed out: - Presently mine was inspected for Review of Mining Plan inspection & Star Rating validation done. Violation under provision of Rules 26(2), 27(1) & 27(2), 28(1), 33 Pointed out for rectification.