

I/2634/2023

Violation Letter
E-MAIL / REGD.A.D

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो

75
साजाधी-
अमृत महोत्सव



75
साजाधी-
अमृत महोत्सव

Government of India
Ministry of Mines
Indian Bureau of Mines

Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, Sector 10A,
Gandhinagar, Gujarat-382010

क्षेत्रीय खान नियंत्रक का कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A गांधीनगर, गुजरात, 382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

फाईल संख्या File No- PORB/LST-048

Mine Code: 38GUJ08001

ID- दिनांक 04.1.2023

सेवा में To : Owner/Agent/Manager/Mining Engineer
प्रेषित : Owner/Agent/Manager/Mining Engineer,
M/s Saurashtra Chemicals, Division of Nirma Limited,
Nirma House, Ashram Road,
Ahmedabad,Gujarat-380009,

Email-mines@nirma.co.in

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Dharampur Kajawadri Limestone Mine over an area of 77.85.54 ha located near Villages- Dharampur Tehsil & District- Porbandar, in Gujarat.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 17.11.2022 AN in the presence of DK Singh, Mine Manager.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	The mining operations were not being carried out as proposed in approved Modified & Review of Mining Plan vide 684(4) (1) MP-324/2020-21-खानिखस(स)/GNR Dated 23.3.2021. Exploration -It was proposed to drill 28 number of DTH borehole, total meters 219.3m as earmarked in plate No.3 but during inspection no such exploratory borehole observed & reported to this office. Exploitation -It was proposed to work for direction of advancement of faces and position of entry ramp as earmarked in page 45-46 and plate no.4A but actual workings has not been carried out as proposed.

- In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- Mining operations can be suspended as per rule 11(2) in case of non-compliance of rule 11(1), as these rules ensures systematic scientific and responsible mining and/or state Government may be informed to take actions as per competent directives.
- This letter has been issued with the approval of Regional Controller of Mines.
- You are advised to rectify the above violation immediately and intimate the compliance position to this office, within 45 days from date of issue of this letter.

भवदीय Yours faithfully,


(जी०राम/G.Ram)

उप खान नियंत्रक /Dy.Controller of Mines

NOO-प्रतिलिपि सूचनार्थ एंव आवश्यक कार्यवाई हेतु प्रेषित :-

- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- आयुक्त, भूविज्ञान एंव खनन, निदेशालय, गुजरात को सूचनार्थ एंव आवश्यक कार्यवाही हेतु प्रेषित ।

उप खान नियंत्रक /Dy.Controller of Mines