



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF
MINES



दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

No. KNT/BLR/FE/ 493 /BNG VOL-II Mine Code 30KAR03184

Date: 11/10/2022

सेवा में/ To,

Nominated Owner
M/s.JSW Steel Limited,
JSW Mining office,
Near Yalur Cross, Vidyanagar Works
P.O. Vidyanagar -583 275, Bellary (District),
Karnataka,

E-mail: jayant.acharya@jsw.in, sunil.singh@jsw.in , nataraja.belegere@jsw.in

Subject: Violation of provisions of MCDR 2017 in respect of in respect of **Bhadra Iron Ore Mine (ML. No 007)** over an area of **130.53 Ha** having mine code **30KAR03184** in Ittanahalli Village, Sandur Taluka, Ballari District, Karnataka state.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 15.09.2023 by Dr. Omkesha Murthy, Regional Mining Geologist in the presence of S/Shri Awadhesh Kumar Rai (Mine Manager), Manjunath Govindappa (Mining Engineer), Nataraj Belgere, Manager (Geology), Binay Kumar, Manager (Survey), Raghavendra S Desai, AGM (Geology) and other officials of your mine.

Rules	Nature of Violations observed
11(1)	Modification to the Approved Mining plan was approved by IBM vide letter no. 279/1093/2017/BNG dated 16/11/2021, for the year 2021-22 (Oct 2021 to March 2022) to 2023-24. The deviations observed in mining operation vis-à-vis approved document is given below i. During the inspection it is observed that huge quantity of processed ore stack (both fines and lump) found in block-1 which has been earmarked for disposal of waste and also between section 1 and 3. Further, in block-1 area a crushing and screening machine is also in operation which is not in accordance with the above referred approved Mining Plan.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(Dr. Suresh Prasad)
Regional Controller of Mines

I/19232/2023

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Regional Mining Geologist