



भारत सरकार GOVERNMENT OF INDIA  
खान मंत्रालय MINISTRY OF MINES  
भारतीय खान ब्यूरो INDIAN BUREAU OF  
MINES  
क्षेत्रीय खान नियंत्रक के कार्यालय  
OFFICE OF THE REGIONAL  
CONTROLLER OF MINES



BY REGD POST A/  
D

Phone: 0674-2352463  
Tele Fax: 0674-2352490  
E-mail: ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput  
BHUBANESWAR-751020

No- MCDR-MiFLOFE/12/2023-BBS-IBM\_R ...

दिनांक -  
08/05/2023

प्रेषित-

Email: Jayant.acharya@jsw.in,

Shri Jayant Acharya, Nominated Owner  
M/s JSW Steel Limited.  
Plot No.200,1<sup>st</sup> floor, Forest Park,  
Near Shishubhawan Square,  
BHUBANESWAR ODISHA-751009

विषय- ओडिशा राज्य के केउंझर जिले में स्थित आपकी गोनूआ लोहा खदान 88.516 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 27.04.2023 by undersigned accompanied by Shri Nikhil Ranjan Behuria, Mine Manager.

Rule	Nature of Violation observed
11(1)	Mining operations are not being undertaken in accordance with the Mining Plan/ Modification of Mining Plan. The Modification of Mining Plan was approved vide letter no. MPM/A/26-ORI/BHU/2021-22/1517 dated 22.02.2022 and following deviation was observed during inspection 1. In 2022-23 the exploration proposed for 14 nos of core drilling of 1400 meter but 10 nos bore hole of 460.95 meter drilling done. 2. The production in 2022-23 proposed for 2.0 million Tons of ROM but achievement is only 0.34 million tons which is only 17 % of the proposal. 3. The development is also not as per proposal and OB generation proposed 207321 cum but actual 33565 Cum generation in 2022-23. 4. During the mine visit it was observed that the proposed environment protection measures not done properly as proposal and Retaining wall of 250m is not constructed. 5. The mine is not developed systematically and bench parameters are not as per proposals and some places (Quarry Gonua) benches are irregular, haphazard working and height of benches are not as per proposals more than 12 meters. It was observed that faces are not developed as per the proposal and some places overhang and big boulders are hanging, toe boulders exist in face and stack near faces.
48(1)	The holder of a mining lease or the holder of a prospecting license or 1 [composite license] shall keep a record in Form-J of all shafts or boreholes and shall retain such records but the same not available.

- इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत  
(क) खान की सारी खनन संक्रियाएँ बंद की जा सकती हैं।  
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।  
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

I/9043/2023

I/9043/2023<sup>2</sup>

(राजेश कुमार दास)  
उप खान नियंत्रक  
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata-700 091.
- (3) The Agent, Goua Iron Mine, JSW Steel Ltd, Plot No-15, Bhusgaon, At-Bhadrsahi, PS-Barbil, District-Keonjhar-758035, e-mail-biswaranjan.padhi@jsw.in

(राजेश कुमार दास)  
उप खान नियंत्रक  
भारतीय खान ब्यूरो, भुवनेश्वर