

1/21153/2023¹

भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF
MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



BY REGD POST A/

D

Phone: 0674-2352463

Tele Fax: 0674-2352490

E-mail:

ro.bhubaneswar@ibm.gov.

in

Plot No.149, Pokhariput

BHUBANESWAR-751020

No-

दिनांक -

15/11/2023

प्रेषित-

Shri Pankaj Kumar Sharma, Nominated Owner
M/s National Aluminium Company Limited.
NALCO Bhawan,P-1,Nayapalli,
BHUBANESWAR ODISHA-751001
e-mail: dirprod@nalcoindia.co.in,
rasheed.waris@nalcoindia.co.in, gm_mines@nalcoindia.co.in

विषय- ओडिशा राज्य के कोरापुट जिले में स्थित आपकी पंपपत्तल्लि सेंट्रल और नॉर्थ ब्लॉक 1315.264 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उलंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 02.11.2023 by undersigned accompanied by Shri Purusottam Mohanta.GM(Mines) & Ajaya Choudhury(Mine Manager)

Rule	Nature of Violation observed				
11(1)	<p>Mining operations are not being undertaken in accordance with the Review of Mining Plan. The Review of Mining Plan was approved vide letter no.RMP/A/22-ORI/BHU/2020-21 dated 09.11.2021 and following deviation was observed during inspection</p> <ol style="list-style-type: none"> The mine is not developed systematically and bench parameters are not as per proposals and bench width proposed 75-100m but many places bench width is 10-15m . It was observed that faces are not developed as per the proposal and some places overhangs and big boulders are hanging and stack near faces and material scattered all along faces. In bottom benches the working is not systematic and selective mining done and ore is excavated in haphazard manner and not as per proposal. The development is also not as per proposal and development is proposed in 21.79 ha. area but actual work done in approximately 9.8 ha. area in 2022-23 (excavation for production of ore, OB and top soil generation) but with same amount of excavation as proposed. Which shows the lateral extent is less but vertical extent is more than proposal. The OB proposed for backfilling in approved document for 2022-23 was 162553 m³ for 1m depth but actual backfilling quantity for 2022-23 is 394150 m³ and depth of backfilling more than 2 m. The Excavation and OB dumping/backfilling is also not as per proposal and proposal is given in for dumping in two dumps but actual dumping is not done and only backfilling done. The details deviation given below: <table border="1"> <thead> <tr> <th>Excavation proposals</th> <th>Actual excavation done</th> </tr> </thead> <tbody> <tr> <td>North Block 2091149.945-2091746.388N to 715924.913-716468.875E Central Block-II 2082096.614- 2082539.187 N to 710052.026- 710540.919E</td> <td>The actual working is done in 3 patches: In Patch 1 & 2 excavation extended outside proposed area & patches 3 no proposal given but excavation done and in patches 4 excavations outside proposed area. Patch1(North Block-I):2091434N-2091376N to 715978E-716058E & 2091122N-2091230N to 716021E-715915E Patch2(North Block-I):2091273N-2091139N to 716228E-716441E & 2091065N-2082435N to 710191E-710154E Patch 3(Central block -II):2082439N-2082435N to 710191E-710154E & 2082242N-2082285N to 710415E-710441,Patch 4 (Central Block-II): 711023.27-711084.84 to</td> </tr> </tbody> </table> 	Excavation proposals	Actual excavation done	North Block 2091149.945-2091746.388N to 715924.913-716468.875E Central Block-II 2082096.614- 2082539.187 N to 710052.026- 710540.919E	The actual working is done in 3 patches: In Patch 1 & 2 excavation extended outside proposed area & patches 3 no proposal given but excavation done and in patches 4 excavations outside proposed area. Patch1(North Block-I):2091434N-2091376N to 715978E-716058E & 2091122N-2091230N to 716021E-715915E Patch2(North Block-I):2091273N-2091139N to 716228E-716441E & 2091065N-2082435N to 710191E-710154E Patch 3(Central block -II):2082439N-2082435N to 710191E-710154E & 2082242N-2082285N to 710415E-710441,Patch 4 (Central Block-II): 711023.27-711084.84 to
Excavation proposals	Actual excavation done				
North Block 2091149.945-2091746.388N to 715924.913-716468.875E Central Block-II 2082096.614- 2082539.187 N to 710052.026- 710540.919E	The actual working is done in 3 patches: In Patch 1 & 2 excavation extended outside proposed area & patches 3 no proposal given but excavation done and in patches 4 excavations outside proposed area. Patch1(North Block-I):2091434N-2091376N to 715978E-716058E & 2091122N-2091230N to 716021E-715915E Patch2(North Block-I):2091273N-2091139N to 716228E-716441E & 2091065N-2082435N to 710191E-710154E Patch 3(Central block -II):2082439N-2082435N to 710191E-710154E & 2082242N-2082285N to 710415E-710441,Patch 4 (Central Block-II): 711023.27-711084.84 to				

		20830.39-2082823.35 & 711000.06-711180.99 to 2082896.29-2082923.29
	Proposal of waste Dumping	Actual Dumping done
	Dumping proposed in two places not done 1.710493E , 2082803N 2.711393E , 2083503N	Not Done
	Backfilling proposals: 2090832.17- 2091407.83 N To 716230.01- 715926.83E	Backfilling done in many places:the point given 1-5 backfilled outside proposed area and 6& 7 backfilled without any proposal. 1.2090785N,716172E 2. 2090666N,716118E 3.2090535N,715911E 4. 2090369N,716044E 5.2090502N,716112E 6.2088543N,714789E 7.2086495N,712858E
12(4)	In the case of existing mining leases, detailed exploration (G1 level) over the entire potentially mineralised area under the mining lease shall be carried out in the manner specified in the Minerals (Evidence of Mineral Contents) Rules, 2015 or the Atomic Minerals Concession Rules, 2016, as the case may be, within a period of five years from the date of commencement of these rules.] But the same not complied.	
45(5) (c)(i)	While scrutiny of Annual returns 2021-22 following discrepancies observed 1. The aluminus laterite resource detailed furnished in return is not as per approved document. 2. There is depletion shown for aluminus laterite resource but resource should not be mined out without converting it to reserves. The dispatch quantity of aluminus laterite shown nil. 3. The production proposal for financial year mentioned as Nil.	

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत
(क) खान की सारी खनन संक्रियाएं बंद की जा सकती हैं।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करें।

भवदीय

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
(2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

I/21153/2023³

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर