#### INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

#### Review and updation of Mining Plan REPORT

#### Chennai regional office

Mine file No : TN/SLM/LST-11/MDS Mine code: 38TMN11027

(i) Name of the Inspecting : K08 ) G.SORNADURAI KANNAN

Officer and ID No.

(ii) Designation : Senior Mining Geologist

(iii) Accompaning mine : Thiru. S.Natarajan, QP & GM-Mines

Official with Designation

(iv) Date of Inspection : 15/10/2023

(v) Prev.inspection date :

PART-I : GENERAL INFORMATION

(a) Mine Name : VEERCHIPALAYAM

(b) Registration NO. : IBM/613/2011

: A Fully Mechanised (C) Category

(d) Type of Working Opencast

(e) Postal address

> State : TAMIL NADU District SALEM

Village : VEERCHIPALAYAM

Taluka SANKARI

Post office : VEERCHIPALAYAM

Pin Code : 637303

FAX No. : 04283-40051

E-mail skd\_mines@indiacements.co.:

Phone : 04283-240382

Police Station : SANKARI (f) First opening date : 10/05/1970 (g)

Weekly day of rest (h) : SUN

Address for : M/S. INDIA CEMENTS LTD., SANKARI WORKS correspondance

SANKARI WEST POST, SALEM - 637 303.

3. : TMN0058 (a) Lease Number (b) Lease area : 75.58 Period of lease : 20 (C)

> : 24/07/1989 (d) Date of Expiry

Mineral worked 4. : LIMESTONE Main 5. Name and Address of the

Lessee : THE INDIA CEMENTS LIMITED

DHUN BUILDING 827, ANNA SALAI CHENNAI CITY TAMIL

NADU

Phone: 044-28521526, 28521527, 28572100, 28572400

FAX :044-28526311

Owner : INDIA CEMENTS LTD

INDIA CEMENT LTD, SANKAR NAGAR POST, TIRUNELVELI DISTRICT. TIRUNELVELI TAMIL

NADU Phone: FAX:

6. Date of approval of Mining : Renewal under rule 24 MCR1960 13/02/2007 Plan/Scheme of Mining Renewal under rule 24 MCR1960 13/02/2007

Renewal under rule 24 MCR1960 13/02/2007
Mining Scheme rule 12 MCDR1988 17/08/2012
Mining Scheme rule 12 MCDR1988 24/06/2014
MP review under 17(1) MCR 2016 20/11/2018

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

## Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	No Boreholes has been proposed during 2022-2023.	No Boreholes has drilled	The mine is not in operation from 2017-2018.
1b	Exploration over lease area for geological axis 1 or 2	No Additional exploration boreholes was proposed over the lease area during 2022-2023	Nil	Entire lease area is proved under G-1 category.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	No Proposal for exploration during 2022- 2023	No Boreholes has been drilled	So far 33 boreholes have been drilled in the lease upto 2022-2023. With total meterage 1208m
1d	Balance area to be explored to bring Geological axis in 1 or 2	Exploration was not proposed during 2022-2023.	No Exploration has been carried out during 2022-2023.	Entire area has been explored under G-1 category with 100m X 100m grid interval.
1e	Balance reserve as on 01/04/20	As on 01.04.2023 Proved Mineral Reserves (111) = 372914 tons Feasibility Mineral Resources (211) = 1170000 tons Inferred Mineral Resources (333) = 380000 tons	As on 01.04.2023 Proved Mineral Reserves (111) = 410000 tons Feasibility Mineral Resources (211) = 1170000 tons Inferred Mineral Resources (333) = 380000 tons	The available grade of Limestone in this lease cement Grade. The mine is not in operation for 2017-2018.
1f	General remarks of inspecting officers on geology, exploration etc	It is part of Archean complex of peninsular gneiss.	The deposit consists of Granite Gneiss and Crystalline limestone intruded by younger granite.	Limestone is medium to coarse grained. More number of intrusions of pegmatite and quartz veins.

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	During 2022- 2023, working proposal was in between section line V1-V2.	Nil	The mine is not in operation from 2017-2018.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	OB - 4 Benches Minerals - 2 Benches	Nil	The mine is not in operation from 2017-2018.
2c	Stripping ratio or ore to OB ratio	1:1.77	Nil	The mine is not in operation from 2017-2018.
2d	Quantity of topsoil generation in m3	No Proposal during 2022- 2023	Nil	The mine is not in operation from 2017-2018.
2e	Quantity of overburden generation in m3	OB Proposed	Nil	The mine is not in operation from 2017-2018.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	proposal was in between	34320 tons of OB Proposed during 2022- 2023	The mine is not in operation from 2017-2018 for statuary clearance.

# Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	Production was Proposed in between section line V1-V2.	Nil	The mine is not in operation from 2017-2018.
3b	Quantity of ROM mineral production proposed	The total target of ROM Production proposed was 51575 tons during 2022-2023.	Nil	The mine is not in operation from 2017-2018.
3с	Recovery of sailable/usable mineral from ROM production	60% Recovery	Nil	The mine is not in operation from 2017-2018.
3d	Quantity of mineral reject generation	20630 tons of Mineral Rejects has proposed.	Nil	The mine is not in operation from 2017-2018.

2 -	C1 1	TT: -1:1:: :	27.2.3	mla
3e	Grade of mineral rejects generation and threshold value declared.	considered as mineral rejects.	NII	The mine is not in operation from 2017-2018.
3f	Quantity of sub grade mineral generation.	No Sub Grade Generation	Nil	The mine is not in operation from 2017-2018.
3g	Grade of sub grade mineral generation	There is No Generation of Subgrade Mineral	Nil	The mine is not in operation from 2017-2018.
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised method	Nil	The mine is not in operation from 2017-2018.
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No Beneficiation Study is Proposed	Nil	The mine is not in operation from 2017-2018.
3j	Provision of drilling and blasting in mineral benches	Drilling & blasting are proposed with 115mm dia holes	Nil	The mine is not in operation from 2017-2018.
3k	Provision of mining machineries in mineral benches	Excavators Tippers Drills Compressor	Nil	The mine is not in operation from 2017-2018.
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	In 2022-2023, Bench height of 10m was proposed in Mineral.	Nil	The mine is not in operation from 2017-2018.
3m	Total area covered under excavation/pits	4.42 hect area is proposed for Pit during 2022-2023	4.42 hect areas are under Pit only.	Proposal of working is within existing pit, so the mined out area is same.
3n	Ore to OB ratio for the pit/mine during the year.	1: 1.77	Nil	The mine is not in operation from 2017-2018.

30	Total area put in use under different heads at the end of year	Land use Pattern as on 01.04.2023. Mines = 4.20 hect Dump = 0.910 hect Roads = 0.80 hect	Land use Pattern as on 01.04.2023. Mines = 4.20 hect Dump = 0.910 hect Roads = 0.80 hect	Landuse pattern is same as per proposal due of non-working of mines.
3p	Production of ROM mineral during the last five year period as applicable	2022-2023 = 51575 tons 2021-2022 = 51600 tons 2020-2021 = 51350 tons 2019-2020 = Nil 2018-2019 = 64000 tons	2022-2023 = Nil 2021-2022 = Nil 2020-2021 = Nil 2019-2020 = Nil 2018-2019 = Nil	The mine is not in operation from 2017-2018 for want of statuary clearance.
3q	General remarks of inspecting officers on method of mining etc.	Proposed in between	The total target of ROM Production proposed was 51575 tons during 2022-2023.	The mine is not in operation from 2017-2018 for want of statuary clearance.

# Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	There is proposal for dumping during 2022-2023	Nil	The mine is not in operation from 2017-2018.
4b	Location of topsoil, OB and mineral reject dumps	OB & Mineral reject dumps are proposed along the Southern side of lease area.	Nil	The mine is not in operation from 2017-2018.
4c	Number of dumps within lease area and outside of lease area	Non Lease area	Lease area = 2 Non Lease area = Nil	Dumps are old and existing as per approved plan.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Outside UPL	Nil	The mine is not in operation from 2017-2018.
4e	Number of active and alive dumps.		Nil	The mine is not in operation from 2017-2018.

4f	Number of dead dumps.	No Proposal	Nil	The mine is not in operation from 2017-2018.
4g	Number of dumps established.	No Dumps have been established.	Nil	The mine is not in operation from 2017-2018.
4h	Whether Retaining wall or garland drain all along dumps are there.		Nil	The mine is not in operation from 2017-2018.
4i	Length of Retaining wall or garland drain all along dumps	along the	Nil	The mine is not in operation from 2017-2018.
4j	Number of settling ponds	No Proposal	Nil	The mine is not in operation from 2017-2018.
4k	Specific comments of inspecting officer on waste dump management		OB & Mineral reject dumps are proposed along the Southern side of lease area.	The mine is not in operation from 2017-2018 for want of statuary clearance.

## Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal for backfilling during 2022- 2023	No backfilling has done during 2022-2023	The mine was not worked upto the proved depth and no backfilling were proposed during 2022-2023.
5b	Area under backfilling of mined out area	No Proposal	Nil	The mine is not in operation from 2017-2018.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No Proposal	Nil	The mine is not in operation from 2017-2018.
5d	Total area fully reclaimed and rehabilitated	No Proposal	Nil	The mine is not in operation from 2017-2018.
5e	General remarks of inspecting officers on backfilling and reclamation etc.	_	The mine was not worked upto the proved depth and no backfilling were proposed during 2022-2023.	The mine is not in operation from 2017-2018 for want of statuary clearance.

### Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	It should be on or before lst July every year.	Submitted for the year 2022-2023.	Submitted within time limit.
6b	Area available for rehabilitation (ha) .	No Proposal	Nil	The mine is not in operation from 2017-2018.
6c	afforestation done (ha).	No Proposal	Nil	The mine is not in operation from 2017-2018.
6d	No. of saplings planted during the year	No Proposal	Nil	The mine is not in operation from 2017-2018.
бе	Cumulative no .of plants	No Proposal	Nil	The mine is not in operation from 2017-2018.
6f	Any other method of rehabilitation	No Proposal	Nil	The mine is not in operation from 2017-2018.
6g	Cost incurred on watch and care during the year	No Proposal	Nil	The mine is not in operation from 2017-2018.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	No Proposal	Nil	The mine is not in operation from 2017-2018.
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No Proposal	Nil	The mine is not in operation from 2017-2018.
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No Proposal	Nil	The mine is not in operation from 2017-2018.
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No Proposal	Nil	The mine is not in operation from 2017-2018.

61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No Proposal	Nil	The mine is not in operation from 2017-2018.
бm	Compliance of rehabilitation of waste land within lease (i)afforestation	7.5m safety zone in lease	55 saplings have planted within lease area during 2022-2023.	Cumulatively 2131 saplings have been planted within lease area upto 2022-2023.
6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	hect in 7.5m	0.10 hect achieved in 7.5m safety zone in lease area for 2022-2023	The mine is not in operation from 2017-2018.
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Green Belt development along 7.5m safety barrier.	Plantation has been done as per proposal along the safety barrier.	The mine is not in operation from 2017-2018.
6p	Compliance of environmental monitoring (core zone and buffer zone)	Bi-Annually Survey	Nil	The mine is not in operation from 2017-2018.
бq	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	50 saplings proposed along 7.5m safety zone in lease area for 2022- 2023	Total 2131 saplings have planted within lease area upto during 2022-2023.	The mine is not in operation from 2017-2018 for want of statuary clearance.

#### Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	The total target of ROM Production proposed was 51575 tons during 2022-2023.	Nil	The mine is not in operation from 2017-2018.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	There is no proposal for grade wise mineral sorting in the lease area.	Nil	The mine is not in operation from 2017-2018.

7c	Different grade of mineral sorted out at mines.	The Limestone of the lease area is cement grade	Nil	The mine is not in operation from 2017-2018.
7d	Any beneficiation process at mines .	Crushing & Screening process at outside the lease area	Inside the lease area there is no beneficiation process.	The mine is not in operation from 2017-2018.
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	Production proposed was	The Limestone of the lease area is cement grade	The mine is not in operation from 2017-2018 for statuary clearance.

### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	during 2022-	Nil	The mine is not in operation from 2017-2018.
8b	Concurrent use or storage of topsoil	No Proposal during 2022- 2023	Nil	The mine is not in operation from 2017-2018.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	There is proposal for dumping during 2022-2023	Nil	The mine is not in operation from 2017-2018.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No Proposal during 2022- 2023	Nil	The mine is not in operation from 2017-2018.
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No Proposal during 2022- 2023	Nil	The mine is not in operation from 2017-2018.

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	7.5m safety	55 saplings have planted within lease area during 2022-2023.	The mine is not in operation from 2017-2018.
8g	Survival rate	No Proposal in the document.	85%	Same has shown in annual return
8h	Water sprinkling on roads to control airborne dust	Yes, it is proposed.	Nil	The mine is not in operation from 2017-2018.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	•	Degraded Mining Land	Outside lease area, agriculture is done with drift irrigation.

# Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	MR Submitted up to = September 2022 AR Submitted up to = 2022- 2023		Both Annual & Monthly returns are submitted in online
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Full time Mining Engineer & Mining Geologist has not shown	Nil	The mine is not in operation from 2017-2018 for want of statuary clearance.
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	01.04.2023. Mines = 4.20 hect	Landuse Pattern is filled as per approved Mining Plan	The mine is not in operation from 2017-2018 for want of statuary clearance.
9d	Scrutiny of Annual return on afforestation	Lessee has planted 55 saplings during 2022-2023.	Nil	The mine is not in operation from 2017-2018 for want of statuary clearance.

9e	Scrutiny of	There is no	Nil	The mine is not in
ЭE	Annual return on mineral reject generation (Grade and quantity)		NII	operation from 2017-2018 for want of statuary clearance.
9f	Scrutiny of Annual return on ROM stock and/or graded ore		There is no production and dispatches during 2022-2023	The mine is not in operation from 2017-2018 for want of statuary clearance.
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Cost of Production & Ex. Mine price has Zero	It is captive mine of M/s. India Cements Ltd.	The mine is not in operation from 2017-2018 for want of statuary clearance.
9h	Scrutiny of Annual return on fixed assets	Fixed Assets is given	Fixed Assets is filled	The mine is not in operation from 2017-2018 for want of statuary clearance.
9k	Scrutiny of Annual return on mining machineries	Machineries details not given	Not available in field due to non-working.	The mine is not in operation from 2017-2018 for want of statuary clearance.

PAGE : 13

Details of violations observed during violation pointed out	g current inspection and compliance position of
Violation observed	Show couse position

Violation observed			Show couse position	
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on Compliance on

#### Date :

(G.SORNADURAI KANNAN)

Indian Bureau of Mines