1/21608/2023



No-

भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



## **BY REGD POST A/**

D

Phone: 0674-2352463 Tele Fax: 0674-2352490 E-mail: ro.bhubaneshwar@ibm.gov.

Plot No.149, Pokhariput BHUBANESWAR-751020

DIIODANL.

दिनांक -06/12/202**3** 

प्रेषिति-

e-mail:gapl\_sponge@yahoo.co.in; neadaghatmines@gmail.com;

Shri C S Grewal, Proprietor, M/s National Enterprises, Post Box No.44, At/Po- Barbil, Dist- Keonjhar, Odisha-758035

विषय-

ओडिशा राज्य के सुंदरगढ़ जिले में स्थित आपकी आदाघत लौह आयेस्क खदान 15.074 हे॰ में खनिज सरक्षण एवं विकास नियमावली 2017 के नियमों के उलंघन के संबंध मे-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 24.11.2023 by undersigned accompanied by Shri P.K.Das, Manager(Mine).

Rule	Nature of Violation observed										
11(1)	Mining operations have not been undertaken in accordance with the Mining Plan/ Review of Mining Plan.  The Mining Plan was approved vide letter no. RMP/A/22-ORI/BHU/2020-21 dated 09.11.2020 and following deviation was observed during inspection  1. During the mine visit it was observed that the proposed environment protection measures not done as mentioned below with location:										
	Period	Retain	ing wall		Garland drain			Settling pond			
		L(m)	B(m)	H(m)	L(m	B(m)	D(m)	No s	L( M)	B(m)	D(m)
	2022- 23(Proposal	200	1.0	1.5	200	1	1	3	10	8	2
	2022- 23(Achieve ment)	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
37(2)	The OB dump shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods. It was observed that there is neither proper terracing and no proper retaining wall is constructed nor any control measures for dump stability taken.										

- इस संदर्भ मे आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंड्नीय अपराध है1 एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2)के अंतर्गत
  - (क) खान की सारी खनन संक्रियाए बंद की जा सकती है1
  - (ख) आपके विरुध अभियोग दायर किया जा सकता है 1
  - (ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है1
- 3 अत: आपको सलाह दी जाती है कि आप उपरोक्त उल्लंधनो का अतिशिघ्र सुधार करे एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सुचित करे।

1/21608/2023

(राजेश कुमार दास) उप खान नियंत्रक भारतीय खान ब्यूरो, भुवनेश्वर

## Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास) उप खान नियंत्रक भारतीय खान ब्यूरो, भुवनेश्वर