



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU
OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



Phone: 0674-2352463
Tele Fax: 0674-2352490
E-mail:
ro.bhubaneswar@ibm.gov.
in
Plot No.149, Pokhariput
BHUBANESWAR-751020

Date: 12.2023

To

The Managing Director & Nominated Owner,
M/s Odisha Mining Corp, Ltd ,
OMC House
Bhubaneswar
Odisha-751001

Sub: Violation of provisions of MCDR, 2017 in respect of your Sukrangi Chromite Mine (Mine Code 11ORI19008) over an area of 382.709 ha in Jajpur distric of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 06.11.2023 by the undersigned, in presence of Shri Manoj Kumar Sethy, Mines manager.

Rule No.	Proposed as per Mining Plan/ Rule Position	Violation
11(1)	As per the Review of Mining Plan approved vide letter No. RPM/A/25-ORI/BHU/2021-22 dated 23.01.2019 it was proposed:- (i) Mining Operation within - 615E to 610E, -100N to 395N (ii) Top soil 63099 CUM OB 1781589 CUM	During inspection it was observed that:- (i) Mining operation carried -530E to 585 E , -90N to 340N (ii) Top soil 4850 CUM OB 448456 CUM
	Production of ROM and Mineral Rejects are less than 50% of the approved quantity. The above deviations constitute violation of Rule 11(1) of MCDR 2017	
45(5)(b)	Discrepancy observed after scrutiny of Monthly returns for the for the year 2023-24 are as follow: (i) Production proposal for the year 2023-24 has not been entered. Thus the entire production is showing as excess production.	

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

Besides, inability to comply with the provisions of Rule 11(1) is liable for suspension of mining operations according to the provisions of Rule 11(2) of MCDR, 2017, further may be recommended for suspension of mining operation under rule 45(7)(a), if rule 45(5)(b) is not complied.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from issue of this letter.

Yours faithfully,

(Sanjay Kumar Mahapatra)
Assistant Controller of Mines

1/21640/2023 Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.
- (3) Shri Manoj Kumar Sethy, Mines Manager, Sukrangi Chromite Mine (Mine Code 11ORI19008) of M/s OMC Ltd, , Dist- Jajpur

(Sanjay Kumar Mahapatra)
Assistant Controller of Mines