

GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES OFFICE OF THE REGIONAL CONTROLLER OF MINES



FAX: 080-23371027/23373287 Tel: 080-23371027/23375366/67 Email ID: ro.bangalore@ibm.gov.in 29, Industrial Suburb, II Stage, Tumkur Road, Gorguntapalya, Yeshwantpur, Bangalore- 560 022.

File no: KNT/DVN/MN/1/BNGMine-code: 40KAR27003Dated: 01/09/2023

सेवामें/ To,

Shri Anup Kumar B.
Managing Partner,
M/s Yerrithatha Mining Company
No. 38, BCM Compound, Infantry Road, Cantonment
Bellary -583 104, Karnataka.

e-mail id: sriyeco@gmail.com

Subject: Violation of provisions of MCDR 2017 in respect of Kadathi Manganese Mine (ML No. 1616) over an area of 2.02 Ha (as per Lease deed) Kadathi Village, Harappanhalli taluka, Vijayanagara District of Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 01/08/2023 by the undersigned and Shri Rohita Sethi, Asst. Mining Engineer in presence of Shri B. Arjun, Managing Partner, Shri Jagadish Vyas, Mining Engineerand other mining officials:

Rules	Nature of Violations observed
11(1)	The Review and Updation of Mining Plan has been approved by IBM vide letter no. 279/933/2006/BNG dated06/01/021 for the period of 2021-22 to 2024-25(Up to 14/02/2025): The deviations observed in mining operation vis-à-vis the approved document are given below: It was observed during site inspectionthat the benches have not been developed as per the proposeddimensions of 6m heightwithin the co-ordinates N1620320 to N1620263 and E589509 to E589561 and mining has been proposed to be carried out up to 598 mRL during the year 2022-23, but it was observed that thoughmininghas been carried out below the proposed mRL(586m),total handling of material seems less including production and the stripping ratio is not justifying with work done.
31 (4)	The plans and sections required under these rules shall be maintained up todate [showing also the respective proposal of approved mining plan for variousactivities pertaining to that year, within three months] in case of category 'A'mines as referred to in clause (a) of sub-rule (2) of rule 55. It was observed during inspection that the same have not maintained as per the provision of this rule.

02. In this connection. It is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.

- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

Sd/(K. Srinivas)

Jr. Mining Geologist
Indian Bureau of Mines

Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-(K. Srinivas) Jr. Mining Geologist Indian Bureau of Mines