



GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES

VIOLATION LETTER
SPEED-POST



FAX : 080- 23371027 / 23373287
Tel : 080-23371027 / 23375366 / 67
Email ID: ro.bangalore@ibm.gov.in

29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.

File no: KNT/DVN/MN/2/BNG

Mine-code: 40KAR27004

Dated: 29/08/2023

सेवा में/ To,

Shri Anup Kumar B.
Managing Partner,
M/s Yerrithatha Mining Company
No. 38, BCM Compound, Infantry Road, Cantonment
Bellary -583 104, Karnataka.
e-mail id: sriyeco@gmail.com

Subject: Violation of provisions of MCDR 2017 in respect of Kadathi Manganese Mine (ML No. 1783) over an area of 12.56 Ha (as per Lease deed) Kadathi Village, Harappanhalli taluka, Vijayanagara District of Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 02/08/2023 by the undersigned and Shri Rohita Sethi, Asst. Mining Engineer in presence of Shri B. Arjun, Managing Partner, Shri Jagadish Vyas, Mining Engineer and other mining officials:

Rules	Nature of Violations observed
11(1)	As per the approved Review and Updation of Mining Plan approved by IBM vide letter no. 279/932/2006/BNG dated 06/01/2021, for the period of 2021-22 to 2025-26: a. It was observed that the benches have not been developed as per proposed dimensions of 6m height within co-ordinates N1620289 to N1620234 and E589633 to E589468 and mining has been proposed to be carried out up to 592mRL during the year 2022-23, but during the site inspection it was observed that mining has been carried out even below the proposed mRL(592m) of the last year of plan period i.e., 2025-26.
31 (4)	The plans and sections required under these rules shall be maintained up to date [showing also the respective proposal of approved mining plan for various activities pertaining to that year, within three months] in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55. It was observed during inspection that the plans have not maintained as per the provision of this rule.

02. In this connection, it is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

Yours faithfully,

Sd/-

(K. Srinivas)

Jr. Mining Geologist

Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(K. Srinivas)

Jr. Mining Geologist

Indian Bureau of Mines