

**Violation letter**  
**By Email/Post**

**GOVERNMENT OF INDIA**  
**MINISTRY OF MINES**  
**INDIAN BUREAU OF MINES**  
**OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Jabalpur, Dated: 19/12/2023.

To,  
**Shri Kailash Chandra Jhanwar**  
M/s Ultratech Cement Ltd  
B Wing Ahura Centre  
2 nd Floor, Mahakali Caves Road  
Andheri (E), Mumbai 400093.

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to **Bhadanpur Limestone Mine , 38MPR35266, Area 296.956 hectare**, in District Satna of Madhya Pradesh.

Sir,

The following provision of Mineral Conservation and Development Rules 2017 were found violated in your above mentioned mine during the inspection by the undersigned on 07.09.2023 in presence of Shri. Rajendra Ambhorkar Manager(Mines) and Shri Saurabh Kumar Jain DGM (Geology).

Rule No	Nature of violation observed in detail
<b>Rule 11(1)</b>	<p><i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.</i></p> <ol style="list-style-type: none"> <li>1. Only 7, 98,830 Tonnes of Limestone was produced against the proposed ROM production of 12,97,295 Tonnes during 2022-2023 which distorting the proposal by 38 %.</li> <li>2. For the reporting year 2022-23 the deviation in the proposed development is observed in between E485000 to E485200, N 2673200 to N2673500 and E485500 to E 485700, N2673300 to N 2673600.</li> <li>3. Workings has been carried out in an area other than the proposed in the last approved Review of mining Plan between the UTM coordinates E 485800 and E 485900 , N 2673400 and N 2673600.</li> <li>4. On North western side of the lease the excavations observed encroaching the of the lease area.</li> </ol>

I/22069/2023

<b>Rule 31(4)</b>	<p><i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine</i></p> <p>The updated plans and sections are not matching with actual field conditions.</p>
-----------------------	---

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
3. Non compliance of rule 11(1) of MCDR, 2017 may lead to suspension of mining operation under the provision of rule 11(2) of MCDR-2017.
4. You are advised to rectify the above violations immediately and intimate the position to this office within a period of 45 days from the date of issue of this letter.

Yours faithfully

(Kathroju Naveen)  
Sr. Asst. Controller of Mines,  
For Regional Controller of Mines,

Copy to:

1. The Controller of Mines (CZ), Nagpur, IBM
2. The Director of Geology & Mining, Government of Madhya Pradesh, Khanij Bhavan, Arera Hills, Bhopal (MP). (All Lease Boundary Pillars not found established to delineate the lease area on the field).
3. The District Collector, Rewa.

((Kathroju Naveen)  
Sr. Asst. Controller of Mines,  
For Regional Controller of Mines,