



भारत सरकार/ GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब ॥ स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं./ No. KNT/BLR/FE/413/BNG

दिनांक/Date: 05/02/2024

सेवा में/ To,

Sri. Alum Prashanth Director IC & Owner,
M/s Suveera Enterprises LLP,
Gadgi Palace, Car Street,
Ballari-583 101.
apmines@yahoo.co.in

विषय/Subject: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Sanjeevarayanakote Iron ore Mine (ML No. 2289) having Mine code: 30KAR03123)** over an area of **42.42 Ha** in Sanjeevarayanakote village, Ballari Taluk & District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri L.Ravi Ramu Naidu, Mines Manager & Mining Engineer, Sri. Nagarjuna, Geologist on 28/12/2023.

Rule	Nature of violations observed
11 (1)	<p>The Mining operations are required to be carried out in accordance with the Review and Updation of Mining Plan document approved vide letter no. 279/584/97/BNG dated 13/11/2020. However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>(i) It is proposed to carry out mining by maintaining all the benches with 8m height and 10m width. However, height and width of few benches between sections F-F' to H-H' are exceeding the proposed height thereby deviating from the approved proposals.</p> <p>(ii) For the year 2022-2023, It was proposed for 89989 tonnes of Iron Ore (BMK) production. However, only 30000 tonnes production is reported thereby achieving only 30 % of the proposed production with more than 200% waste removal deviating from the approved proposals and not achieving the proposed stripping ratio.</p>

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(H.M. SHIVAKUMAR)
Assistant Controller of Mines
Indian Bureau of Mines

प्रतिलिपिसूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

(H.M. SHIVAKUMAR)
Assistant Controller of Mines
Indian Bureau of Mines