

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, C Wing, Sec 10A
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: LST/69/2022-GNR-IBM_RO_GNR

दिनांक: 22.12.2023

Mine code 38GUJ08155

सेवा में : हरनासा चुना पत्थर खान

जी एच सी एल ,

तालुका – सुतरापाड़ा जिला – जूनागढ़ , गुजरात -362 268

e mail – khushbookumar@ghcl.co.in, devanandroy@ghcl.co.in

विषय: गुजरात राज्य के जूनागढ़ जिले की सुतरापाड़ा तालुका में स्थित आपकी हरनासा चुना पत्थर खान क्षेत्रफल- 141.85 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का स्टार रेटिंग/एम.सी.डी.आर निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 05.12.2023 को श्री देवानंद रॉय खान प्रबन्धक, चन्दन कुमार, भूविज्ञानी अन्य की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं./Rule No	उल्लंघन के प्रकार का विस्तृत ब्यौरा/ Detailed description of the type of violation				
34(A)	In the Digital Aerial Images submitted under Rule 34(A), it is observed that the processed Drone survey output data submitted to Indian Bureau of Mines does not meet the parameters specified in the SOP for submission of Digital Aerial Images under the said Rule. The deviations in the data submitted is as follows:-				
	Sl. No.	Data type	Check Point parameters as per SOP	Submitted in proper format (Yes/No)	Remarks
		Orthomosaic image	Resolution	Partly	Full image

I/22341/2023

1	of lease area including 100m buffer zone.	5cm	Submitted	is not displaying
2	Digital Elevation Model (3D) – DTM	Resolution 15cm	No	DTM Resolution 16 cm
3	Excavated Area, Subgrade dump, Backfilled, reclaimed and rehabilitated area	.shp (UTM in WGS 84)	No	Polygons not closed. Area couldn't be determined

45(5)(c) read with 45(7)

वर्ष 2022-23 के लिए आपके द्वारा प्रस्तुत वार्षिक विवरणी की संवीक्षा में निम्न कमी पाई गई है –

1. पार्ट – I, बिन्दु 11 में lease क्षेत्र शून्य दर्शाया गया है जबकि राज्य सरकार द्वारा दिये गए खनन पट्टे का विवरण प्रस्तुत किया जाना चाहिए था ।
2. पार्ट – VI, बिन्दु 2 और 3 के अनुसार 144021 MT, ROM का उत्पादन तथा 135868.850 MT ग्रेडवार उत्पादन रिटर्न में दिखाया गया है। हालाँकि शेष 8152.15 मीट्रिक टन की मात्रा सबग्रेड-मिनरल रिजेक्ट कॉलम में नहीं दिखाई गई है ।
3. Dispatch किए गए खनिज के लिए भुगतान की गई रॉयल्टी प्रति टन रॉयल्टी की निर्धारित दर से कम दर्शाई गई है।

The following deficiencies have been found in the scrutiny of the annual return submitted by you for the year 2022-23 –

1. In Part-I, point 11, lease area has been shown as zero whereas details of mining lease granted by the State Government should have been presented.
2. As per Part – VI, point 2 and 3, production of 144021 MT of ROM and 135868.850 MT of grade wise production is shown in the return. However the remaining quantity of 8152.15 MT is not shown in the Subgrade-Mineral Reject column.
3. The royalty paid for the mineral dispatched is shown to be less than the prescribed rate of royalty per tonne.

1. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
2. You are also liable to pay an amount of Rs.10000/-**per day** for such days as per **Schedule-II**, read with Rule 45(7A) in case of non-compliance of various provisions of Rule 45.
3. As per provision of Rule 45(7) and/or 45(7A)(ii) the Regional Controller of Mines may take appropriate action including order of suspension of **all mining operations and dispatches** on non-compliance of various provisions of Rule 45.

I/22341/2023

4. In context to the violations of Rule **45**, this letter has been considered as show cause notice where you are advised to rectify above violation immediately. You are therefore directed to show cause within a period of **30 days** from the date of issue of this letter as to why the action under Rule **45(7) and/or 45(7A)** shall not be taken against you. No further notice will be given to you in this regard
5. Further, violation of Rule 34(A), you are advised to rectify the above violations immediately and re-submit the data to this office and **also to Chief Mining Geologist, Indian Bureau of Mines, Nagpur within 45 (Forty Five) days** from the date of issue of this letter.
6. You are advised to rectify the above violation immediately and intimate the compliance position to this office, within 30 days in case of comply of rule of 45 and within 45 days for other violated rule from date of issue of this letter.
7. यह उल्लंघन पत्र सह कारण बताओ नोटिस क्षेत्रीय खान नियंत्रक के अनुमोदन पश्चात जारी किया जा रहा है।

भवदीय

(मोहम्मद निमर)

उप खान नियंत्रक

भारतीय खान ब्यूरो

प्रतिलिपि - १. खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर को सूचनार्थ प्रेषित।

२. खनिज सांख्यिकी प्रभाग, भारतीय खान ब्यूरो, नागपुर mms@ibm.gov.in को सूचनार्थ तथा Refer back करने की कार्यवाही हेतु प्रेषित।

२. आयुक्त, भू विज्ञान एवं खनन, गुजरात सरकार, पुराना सचिवालय, ब्लॉक न.- 15, डा जीवराज मेहता भवन, सैक्टर- 10, गांधीनगर को सूचनार्थ प्रेषित।

३. रक्षित पत्रावली।

उप खान नियंत्रक

भारतीय खान ब्यूरो