



भारत सरकार/ GOVERNMENT OF INDIA  
खान मंत्रालय/ MINISTRY OF MINES  
भारतीय खान ब्यूरो/ INDIAN BUREAU OF  
MINES  
क्षेत्रीय खान नियंत्रक कार्यालय/  
OFFICE OF REGIONAL  
CONTROLLER OF MINES

**VIOLATION LETTER**

फैक्स: (080) 23371027 /  
23373287  
दूरभाष: 080-23371027 /  
23375366/67  
Email ID: ro.  
bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,  
गोसुंटापाल्या येशवंतपुर,  
बेंगलुरु -560022

सं./No. MCDR-MiFLOMn/1/2023-BNG-IBM\_RO\_BNG

दिनांक/Date: 10/04/2024

सेवामें/ To,

**Shri. Bharat Kantial Parikh, Nominated Owner,**  
**Hulikatte Manganese Mine,**  
**M/s Bharat Parikh & Company**  
703/179, "Shankarkrupa" 4<sup>th</sup> Main, 5<sup>th</sup> Cross,  
Anjaneya Layout, Davanagere- 577 004  
Email: bpcoco@gmail.com

**विषय/Sub :-** Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Hulikatte Manganese Mine ( ML No. 2571) over an extent of 32.23 Ha having **Mine Code 40KAR07009** located in Gudahalu village, Jagalur & Davanagere Taluk, Davanagere District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 21.03.2024 by Shri. Gangadhar Bhakat, AME in the presence of Sri. Kush A. Shirodkar, Mines Manager and other mine officials.

Rule	Nature of violations observed
11(1)	<p>The Mining operations are required to be carried out in accordance with the approved Review and Updation Mining Plan document vide letter no. 279/131/89/BNG dated 03.02.2020, However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>i. During the year 2022-23, it was proposed to produce Manganese Ore (ROM) of 40045 tonnes by handling</p>

	<p>60643m<sup>3</sup> of waste. However, only 9005 tonnes of Manganese Ore produced by handling 13500m<sup>3</sup> of waste/OB. Only 22% of proposed production and development is achieved during the year.</p> <p>ii. As per the proposal for the year 2022-23 the lessee has to be constructed garland drain of 135m. However, it is observed during the inspection that only 15m of garland drain has been constructed.</p>
--	---

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

04. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(H. M. Shivakumar)  
Assistant Controller of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines

**प्रतिलिपि सूचनार्थ'/Copy for kind information to:**

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, MMS Division, Indian Bureau of Mines, Nagpur.
3. The Director, Department of Mining & Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

(H. M. Shivakumar)  
Assistant Controller of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines