

I/15937/2023



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF
MINES



फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in

सं/No.: KNT/BLR/Fe/437/BNG

सेवा में / To:

Shri B Rudra Gouda

Nominated Owner

M/s BKG Mining Private Limited.

2198, BKG House, KHB Colony

Sandur, Ballari Dist. 583 119

Email: geosurvey@bkggroup.com

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या, येशवंतपुर,

Bengaluru/ बेंगलुरु -560022

दिनांक/Dated: August /2023

विषय/Subject: Violation of provisions of MCDR, 2017 in respect of your Haddinapade Iron Ore Mine (ML No. 24516) over an extent 79.806, located in Hulikunte, SM Block village, Sandur Taluk, Bellary District, Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 22/08/2023 by undersigned in presence of Shri P. Sreenivasa Rao, GM-Mines, Shri Pramod S Ritti, Dy. GM-Geology, Shri Naresh Kakumanu and Sr. Manager-Mines

Rules	Nature of Violations observed
11(1)	<p>The Mining operations required to be carried out in accordance as per the approved Modifications in the Review and Updation of Mining Plan document vide letter no. 279/767/2003/BNG dated 12/10/2021, However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>During the year 2022-23, it was proposed to dispose the waste at two locations viz. PTD-1 and AD-1 dumps. The coordinates for these dumping locations were provided are as follows: PTD-1: N.1662562 - 1662646 and E. 665944 - 666014 and AD-1: N. 1662087 -1662057 and E. 666070 – 666159. However, during the inspection, it was observed that the proposed waste dumping at AD-1 did not take place as intended. Additionally, at the dump site PTD-1, the waste dumping had exceeded the originally proposed limit. The extension was approximately 60 meters in the eastern direction.</p>

I/15937/2023

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist