1/30484/2024

Violation Letter By Speed- Post

## भारत सरकार/Government of India खान मंत्रालय/Ministry of Mines भारतीय खान ब्यूरो/Indian Bureau of Mines



## क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/Office of the RCOM, Goa

Phone No.: (0832)-2741757 Opp. R.T.O. Office, Fax No. : (0832)-2741758 P.O. FATORDA – 403

602,

सतत कार्यरत ON WITH THE JOB

E-mail : ro.goa@ibm.gov.in MARGAO - GOA.

No: MCDR-MiFL0LST/11/2023-GOA-IBM RO GOA Date: 26/04/24

Mine Code: 38KAR26022

सेवा में/ To,

Smt. Pooja M. Udapudi, Legal representative of late Shri B.C. Udapudi Lokapur, Main Bazar Road, Mudhol Taluka, Bagalkot District.

Karnataka: 587 122

विषय/Subject: Violations of MCDR provisions in respect of Muddapur Limestone & Dolomite Mine (ML No. 2534), Extent 14.569 Ha., situated in Muddapur Village, Mudhol Taluk, Bagalkot District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 05.10.2023 by the undersigned in the presence of Smt P. Udapudi – Mine Owner, Sh. Shivraj- Mining Engineer, and other mining officials:

Rules	Nature of Violations observed
11 (1)	The mining operation in the leasehold area is not carried out as per the Modification in the approved Mining Plan dated 03/03/2022 to the extent mentioned below:  a) The bench parameters in the pit are not maintained properly. The height & width of the benches are not found as per the approved document in many places. b) General Cleanliness and maintenance of pit bottom & benches in the mines area is found in a meager condition. In the bottom of the pit, small and unsystematic heaps of the material were observed.
	c) Production of Limestone Ore & Mine development is reported NIL against the approved proposal of 60,000 Tonnes & 2667 m3 respectively.

02. It is brought to your notice that violation of the above Rule constitutes an offense punishable under Rule 62 of MCDR, 2017.

## MCDR-MiFLoLST/11/2023-GOA-IBM\_RO\_GOA

- 1/30484/202**6**3. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
  - 04. You are advised to rectify the above violations immediately and intimate the position to this office within <u>45 (Forty-Five) days</u> from the date of issue of this letter.

भवदीय/Yours faithfully,

( नरेश कुमार कटारिया ) क्षेत्रीय खान नियंत्रक, क्षेत्रीय कार्यालय-गोवा, भारतीय खान ब्यूरो

## Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- **2.** The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

( नरेश कुमार कटारिया ) क्षेत्रीय खान नियंत्रक