1/31243/2024

Violation letter By Speed Post



भारत सरकार/Government of India खान मंत्रालय/Ministry of Mines भारतीय खान ब्यूरो/Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/Office of the RCOM, Goa

<u>आईएसओ**-9001:201**5)</u>

Phone No.: (0832)-2741757 Opp. R.T.O. Office, Fax No. : (0832)-2741758 P.O. FATORDA – 403

602.

(

E-mail : ro.goa@ibm.gov.in MARGAO - GOA.

NO: MCDR-MiFL0LST/5/2023-GOA-IBM RO GOA Mine Code: 38KAR26070

सेवा में/ To,

Shri L.S. Hiremath

At & PO: Lokapur, Mudhol Taluk

Bagalkot District. Karnataka: 587122

विषय/Subject: Violations of MCDR provisions in respect of Lokapur Limestone Mine, ML No. 2575 of Shri L.S. Hiremath, Extent 4.05 Ha., located at Lokapur Village, Mudhol Taluk, Bagalkot District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 04.03.2024 by undersigned in the presence of S/Shri L.S. Hiremath- Lessee and other mining officials:

other mining officials.	
Rules	Nature of Violations observed
	The mining operation is not carried out as per the Modified Mining
	Plan approved by IBM dated 24/01/2022, for the period of 2022-23 to
11 (1)	2026-27 due to the following reason:
	 a. The bench parameters in the pit are not maintained as per the approved document. The benches' height is almost double the approved height in many places. The width of the benches is not properly maintained as per the provision of the statute. b. General Cleanliness and maintenance of pit bottom & benches in the mines area is found in a meager condition. In the bottom of the pit, small and unsystematic heaps of the material were observed. c. The ROM was found stacked along the 7.5m safety barrier of the mining lease area.

02. It is brought to your notice that violation of the above Rule constitutes an offense punishable under Rule 62 of MCDR, 2017.

MCDR-MiFLOLST/5/2023-GOA-IBM_RO_GOA

- 1/31243/202*03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
 - 04. You are advised to rectify the above violations immediately and intimate the position to this office within <u>45 (Forty-Five) days</u> from the date of issue of this letter.

भवदीय/Yours faithfully,

(नरेश कुमार कटारिया) क्षेत्रीय खान नियंत्रक, क्षेत्रीय कार्यालय-गोवा, भारतीय खान ब्यूरो

Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- **2.** The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

--sd--(नरेश कुमार कटारिया) क्षेत्रीय खान नियंत्रक