

I/6855/2023

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
माखपुर औद्योगिक क्षेत्र अजमेर
305002



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of
Mines. Makhupura Industrial Area,
Ajmer- 305002

Ph-145-2695165 / 2695476 Fax-
2695202

ई-मेल : ro.ajmer@ibm.gov.in

संख्या : **E3152 MCDR-MiFLOLST/9/2022-AJM-IBM_RO_AJM**

दिनांक : 24.03.2023

To : Mine Agent, Mohrai Dangla Limestone Mine,
M/s Ulteratech Cement Ltd.,
Khasara No 1146, Tunkra Balara road,
Village- Balara, Tehsil- Jaitaran
Dist-Pali, Rajasthan-306709.
(E-mail: kushal.jain@adityabirla.com),

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Mohrai Dangla Limestone Mine over an area 689.76 Ha.in Sirohi district of Rajasthan State.
egksn;]

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 11/03/2023 by the undersigned in presence of Shri K.C. Jain, Agent and Shri Deepak Kumar Sharma, Mines Manager.

Rule No.	Nature of violation observed in detail
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Modified Mining Plan (Approved on 23.11.2020): - 1. During the year 2021-22 and 2022-23 (upto feb, 2023): 2.44 million tonnes and 5.77 million tonnes ROM production were proposed during the year 2021-22 and 2022-23, but 0.0159 million tonnes and 0.792(upto feb 2023) million tonnes ROM production carried out against this proposal which is around 0.65 % and 13.72% of the proposal respectively. Such low achievements in production has substantially changed pit profile effecting all subsequent year also.
Rule 40	Every holder of prospecting licence or a mining lease shall take all possible measure to keep air pollution due to fines, dust, smoke or gaseous emissions during prospecting, mining, beneficiation or metallurgical operations and related activities within permissible limits. During the Inspection, It was observed that effective water sprinkling arrangement for dust suppression was not provided at crusher hopper.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियम का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अन्तर्गत:

- (क) आपकी खदान की सारी संक्रियाएं बंद की जा सकती है ।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है ।
(ग) खनन पट्टा खंडन की अनुसंशा की जा सकती है ।

03. अतः आपको यह निर्देशित किया जाता है कि आप उपरोक्त उल्लंघन का अतीशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालीस) दिवस के भीतर इस कार्यालय को प्रेषित करें ।

भवदीय

(चन्द्रेश बोहरा)

उप खान नियंत्रक(कार्यालय प्रभारी)
भारतीय खान ब्यूरो

P.T.O.

Copy for kind information to:

1. The Controller of Mines (NZ), Indian Bureau of Mines, Udaipur (Email)
2. The Director, Directorate of Mines & Geology, Govt. of Rajasthan, Shastri Circle, Udaipur (Raj.).
3. The Mining Engineer, Department of Mines & Geology, Govt. of Rajasthan, Pali district (Rajasthan).

उप खान नियंत्रक(कार्यालय प्रभारी)
भारतीय खान ब्यूरो