

I/33544/2024



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय /
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in

सं/No.: MCDR-MiFLOFE/4/2022-BNG-IBM_RO_BNG

Minecode:30KAR533001

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या, येशवंतपुर,
Bengaluru/ बेंगलुरु - 560022

दिनांक/Dated: 13/06/2024

सेवा में/ To,

Smt. B.L. Rani Samyuktha

#52, 2nd Cross, Huda Office Lane,
Shanthinagar, Hosapete – 583 201
Vijayanagara District, KARNATAKA
Email: samyuktha.sri99@gmail.com

Subject: Violation of provisions of MCDR 2017 in respect of your Doddabyladakere Iron ore Mine (ML No. 021) over an extent of 60.92Ha located in Doddabyladakere Village, Chitradurga District of Karnataka State.

महोदय/Sir,

The following provisions of the Mining Conservation and Development Rules, 2017 were found violated in your mine during the inspection carried out on 06/06/2024 by undersigned in presence of Sri. Prakash Y, Mines Manger, Shri Abhay S, Geologist and other mine officials.

Rules	Nature of Violations observed
11(1)	<p>The mining operations are required to be carried out in accordance with the approved Mining Plan document, as per letter no. MCDR-MPC0FE/7/2023-BNG-IBM_RO_BNG dated 16/06/2023. However, during the inspection, deviations were observed in the mining operations vis-à-vis the approved document. These deviations are as follows:</p> <p>During the first year (2023-24), it is proposed to use a total area of 7.67 ha for mining, 5.43 ha for dumping, and 0.21 ha for mineral storage. However, as per the updated Surface Plan (as on 31/03/2024), it is observed that the total area under mining is 10.43 ha, under dumping is 6.79 ha, and under the stockyard is 8.28 ha, which is not convincing.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

- 1/33544/2024
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
 04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

प्रतिलिपि सूचनार्थ / Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist