Violation Letter Speed Post/Email

भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES

29, इंडस्ट्रियल सबर्ब, ॥ स्टेज, तुमकुर रोड,

दूरभाष: (080) 39505368 / 29720499 Email ID: ro. bangalore@ibm.gov.in

गोरगुंटापाल्या येशवंतपुर, बेंगलुरु -560022

To,

Shri Gajraj Singh Rathore,

Nominated Owner, Bhomman iron ore mine

M/s. JSW Steel Ltd JSW Mining office

Near Talur Cross, Vidyanagar Works

Po-Vidyanagar, Dist-Ballari, Karnataka-583275

E-mail id- gajraj.rathore@jsw.in; sunil.singh@jsw.in, Srinivas.nr@jsw.in

विषय/Subject: Violation of provisions of MCDR 2017 in respect of your Bhomman *Iron ore mine*, ML 0014 over an extent of 93.60 ha, in Bedarabommanahalli, Hirekandavadi & other Villages, Holalkere & Chitradurga Taluk, Chitradurga District of Karnataka State.

Sir

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 13.06.2024 by the undersigned in presence of Shri Sanjeev Kumar, AVP(Mines), Shri Srinivas N R, Mine Manager & Mining Engineer, Shri Deepak Patil B.S. Geologist and other mine officials:

Patil B.S, Geologist and other mine officials:								
Rules	Nature of Violations observed							
11 (1)	The Modifications to the approved Mining Plan was approved by IBM vide letter no. 279/1104/2019/BNG dated 29/03/2023 for the period 2022-23 (01/01/2023 to 31/03/2023) to 2024-25 The deviations observed in mining operation vis-à-vis approved document are given below.							
	 i. The stripping ratio proposed for the year 2023-24(Ore: waste) is 1:0.03 against which 1:0.01 has been achieved. Less development & corresponding waste handling (36,991 tons/ 20,550.56 Cum) has been carried out proportionate to achieved ROM production of 27,99,877 tons. Accordingly, development of benches at North western portion of pit is lagging between section F-F' to H-H' (N-1571680, E-631502 to N- 1571590, E-631465) as per proposal. ii. It is observed during inspection that some mineral stacks are located at Section G-G' & H-H' at North western portion, which is restricting the bench advancement at Nortwestern portion of pit as per the proposal. iii. As per the special conditions B. (3) of mine plan approval letter dtd 29/03/2023, the integrated Slope stability study (Mine pit & Waste dumps) and the Hydrological Study of the Mine shall be carried out by the Government agencies and reports to be submitted to this office at the earliest. The abovementioned study reports have not been submitted to this office as on date of 							

MCDR-MiFLOFE/24/2023-BNG-IBM_RO_BNG

1/34312/2024

this office	inspection,	as nei	r the	mine	nlan	condition
uns onice	mspection,	, as pei	uic	11111111	piaii	COHUILIOH.

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(Sandeep Kumar Singh) Senior Assistant Controller of Mines Indian Bureau of Mines

Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001

(Sandeep Kumar Singh) Senior Assistant Controller of Mines Indian Bureau of Mines