

I/33998/2024



भारत सरकार/ Government of India

खान मंत्रालय / Ministry of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



To,

श्री मदन लाल ग्रोवर (मालिक),  
सलैया-पहरहाई चूना पत्थर खदान,  
सिविल लाइन्स, पोस्ट-कटनी,  
जिला-कटनी (म.प्र.)-483501  
ईमेल – ranjan\_grover4@yahoo.com

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Salaiya-Paharhai Limestone Mine over an extent of 9.84 hectares in Vijayraghavgarh Tehsil, in Katn District of Madhya Pradesh State

Sir,

Shri Abhishek Ranjan Gautam, Assistant Mining Engineer inspected your mine on 30/05/2024 in the presence of your representative Shri Manoj Kumar Roy, Shri Arvind Tamrakar (Geologist) and other mines officials. The document of above mentioned mine was approved vide letter No. MP/Katni/Limestone/MPLN/MOD-45/2018-19 dated 17.06.2019 incorporating proposal of working from 2019-20 to 2023-24. Following provisions of MCDR 2017 (as amended up to 3rd November, 2021) were found violated in your mines at the time of inspection.

Rule No.	Proposal/ Rule Position	Nature of Violation
	As per CCOM guideline all boundary pillars are need to be fixed in appropriate location.	Physical appearance of most of the boundary pillar were not observed in appropriate location as per their coordinates marked on them in the lease area. Boundary Pillars need be fixed based on DGPS Report.
11(1)	As per statutory provisions, 7.5 meter barrier zone of lease boundary must be kept in original position. However lessee has taken permission of common lease boundary from Director, Directorate of Mine Safety, Jabalpur vide their letter dated. 27/07/2019.The validity of said permission already expired one year back i.e on 03/05/2022.	During the inspection it wa observed that permission of competent authority related with common boundary had not acquired and submitted to this office so far.

I/33998/2024

31(4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in case of any other mine	The plans & sections were not found updated on quarterly basis as required under this rule and not maintained at mines site office.
33	Copies of plans and sections to be submitted – The holder of mining lease shall on or before the 30th day of the June every year submit to the authorized officer, as the case may be, and the State Govt., a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32.	Copies of plans and sections under rule 32 of MCDR-2017 have not been submitted.

02. Further, it is brought to your notice that the above violations constitute an offense punishable under rule 62 of Mineral Conservation and Development Rules, 2017.
03. Further, non-compliance of the rule 11(1) of MCDR, 2017 may lead to the suspension of mining operations under the provisions of rules 11(2) of Mineral Conservation and Development Rules, 2017.
04. You are therefore advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

भवदीय,

(माधवराव साबरे)  
वरिष्ठ खनन भूविज्ञानी  
कृते क्षेत्रीय खान नियंत्रक  
भारतीय खान ब्यूरो

प्रतिलिपि प्रेषित (ईमेल) : \_\_\_\_\_

01. संचालक, भौमिकी एवम खनिकर्म, मध्य प्रदेश सरकार, खनिज भवन, 29-ए, अरेरा हिल्स, भोपाल (म.प्र.) को सूचनार्थ एवं अग्रिम कार्रवाई हेतु.
02. खान नियंत्रक (मध्यांचल), भारतीय खान ब्यूरो, नागपुर
03. जिलाधीश, जिला – कटनी (म.प्र.) सूचनार्थ ।

(माधवराव साबरे)  
वरिष्ठ खनन भूविज्ञानी  
कृते क्षेत्रीय खान नियंत्रक  
भारतीय खान ब्यूरो