



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय /
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या, येशवंतपुर, बेंगलुरु
29, Industrial Suburb, II Stage,
Tumkur Road, Goruguntapalya,
Yeshwantpur, Bangalore – 560022

सं/No.: MCDR-MiFLOFE/4/2023-BNG-IBM_RO_BNG

Minecode: 30KAR03065

सेवा में/ To,

Shri Ajay Saraf

Nominated Owner

M/s RAI BAHADUR SETH SHREERAM NARASINGDAS PVT LTD

D/No. 1499/1, PO Box No. 38,, Kariganur Post,

HOSAPETE, Vijayanagara Dist. - 583201

e-mail: office@rbssn.com

विषय/**Subject** : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your in respect of your Sankalapuram Iron ore mine (ML No. 2682) over an extent of 111.09Ha located in Sankalapuram Village, Vijayanagara District of Karnataka State

महोदय/Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 19.08.2024 by undersigned in presence of Shri Lakshminarayana, Senior General Manager, Shri Gopal Joshi, Mine Manager, and other Mine officials

Rule s	Nature of Violations Observed
11(1)	The Mining operations are required to be carried out in accordance with the approved Modifications to the approved Mining Plan document vide letter no. MCDR_MPC0FE/10/2023-BNG-IBM_RO_BNG dated 07/11/2023. However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows: (i) For the year 2023-24, it was proposed to extract ROM from Pit No. P-4 between section lines S-14 and S-15, maintaining a bench height of 7 meters and a width of 8 meters. However, during the inspection, it was observed that the proposed height and width of the benches were not maintained. (ii) For the year 2023-24, it was proposed to develop a green belt within

I/38330/2024

	the safety zone of the core area (0.79Ha area) by planting 1,580 plants. However, upon inspection, it was found that the proposed plantation at the specified location was not carried out.
--	---

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

प्रतिलिपि सूचनार्थ / Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist