

# GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES OFFICE OF THE REGIONAL CONTROLLER OF MINES





Jabalpur, Dated: 22.12.2023

To,

## Smt Priyanka Sharma (Nominated Owner)

M/s Narayan Metals and Mineral Dhukan No 03, Bengali Club Market, Karamchand Chowk, Jabalpur (M.P)-482001.

Email: nayrayanminerals01@gmail.com

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to your Gosalpur manganese, iron ore, Blue dust Mine, Mine Code **40MPR18017** over an area of 12.77 hect; situated in Village – Gosalpur, District: - Jablpur of M.P.

Sir,

The following provision of Mineral Conservation and Development Rules 2017 were found violated in your above mentioned mine during the inspection by the undersigned on 02.11.2023 in presence of Shri. Sanjay Tiwari (Lessee representative) and Indraneel Dhawande Q.P

Rule No	Nature of violation observed in detail
Rule 11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.
	<ul> <li>i. It is observed that Mine working have been encroached the 7.5m barrier in between the boundary pillars No. BP 04 and BP 03</li> <li>ii. The Waste dump found extending outside the lease area in the Northern side.</li> <li>iii. Mineral Stack in the northern direction is being encroached by the waste dump of the adjacent mine which causing dilution of mineral.</li> </ul>
	iv. Bench heights are not maintain systematically which resulting creation of high wall.
Rule 12(4)	In the case of existing mining leases detailed exploration (G1 level) over the entire potentially mineralised area under the mining lease shall be carried out within a period of five years from the date of commencement of these rules.
	The Mining lease area has not been explored under G1 level over the entire potentially mineralized area.
Rule 31(4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine.
	The plans and sections have not been updated as required.

# MCDR-MiFLOFE/17/2023-JBP-IBM\_RO\_JBP

### 1/22381/2023

- 2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- 3. You are advised to rectify the above violations immediately and intimate the position to this office within a period of 45 days from the date of issue of this letter.

Yours faithfully

(Kathroju Naveen) Sr. Asst. Controller of Mines, For Regional controller of Mines, Jabalpur.

### Copy to:

- 1. Controller of Mines, COM(CZ).
- 2. The Director of Geology & Mining, Government of Madhya Pradesh, Khanij Bhavan, Arera Hills, Bhopal (MP)( As the Mining Boundary is encroached by the Pit.)
- 3. The District Collector, Jabalpur

(Kathroju Naveen) Sr.Asst. Controller of Mines, For Regional controller of Mines, Jabalpur