1/34024/2024

भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines



क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines

To,

श्री सुखदेव प्रसाद गोयनका, (मालिक) हरैया चूनापत्थर खदान, गोयनका भवन, स्टेशन रोड कटनी, जिला - कटनी, मध्य प्रदेश -483501

ईमेल - ashokchunawala5555@yahoo.com, alokgoenkakatni@gmail.com

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Harraiya Limestone Mine over an extent of 7.605 hectares in Vijayraghavgarh Tehsil, in Katn District of Madhya Pradesh State

Sir,

Shri Abhishek Ranjan Gautam, Assistant Mining Engineer inspected your mine on 30/05/2024 in the presence of your representative Smt Gunjan Goenka, Shri Krishna Gautam, (Mining Engineer) and other mines officials. The document of above mentioned mine was approved vide letter No. E 8085 MCDR-MPC0LST/26/2023-JBP-IBM_RO_JBP dated 31.10.2023 incorporating proposal of working from 2023-24 to 2027-28. Following provisions of MCDR 2017 (as amended up to 3rd November, 2021) were found violated in your mines at the time of inspection.

| Rule No. | Proposal/ Rule Position | Nature of Violation |
|----------|--|---|
| 11(1) | During the year 2023-24, it was proposed to drill 06 numbers of boreholes and their locations were marked in the approved Surface Geological plan. | In 2023-24, 06 numbers of boreholes were drilled but these boreholes were not drilled as per their proposed location shown in the approved Surface Geological plan. |
| | Backfilling was proposed near pit 1 towards NE part of Barrier zone of the lease. | As per proposal, Backfilling was not done near pit 1 towards NE part of Barrier zone. |
| | It was proposed to produce 381839 metric tons of Limestone in the year 2023-24. | Actual Limestone production during the year was less i.e., 247225 tons. The limestone production was lagging from the approved proposal. |
| | 400 numbers of sapling was proposed during the year 2023-24 | Plantation on proposed site found not carried out. |
| 19 | The log books may be maintained in electronic form or in hard copy and shall be made available to the authorised officer on demand. | Log book of Machinery deployed in mines was not maintained properly. |

- 02. Further, it is brought to your notice that the above violations constitute an offense punishable under rule 62 of Mineral Conservation and Development Rules, 2017.
- 03. Further, non-compliance of the rule 11(1) and 19 of MCDR, 2017 may lead to the suspension of mining operations under the provisions of rules 11(2) of Mineral Conservation and Development Rules, 2017.
- 04. You are therefore advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

MCDR-MiFLOLST/57/2023-JBP-IBM_RO_JBP

1/34024/2024

भवदीय,

(माधवराव साबरे) वरिष्ठ खनन भूविज्ञानी कृते क्षेत्रीय खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि प्रेषित (ईमेल):

- 01. संचालक, भौमिकी एवम खनिकर्म, मध्य प्रदेश सरकार, खनिज भवन, 29-ए, अरेरा हिल्स, भोपाल (म.प्र.) को सूचनार्थ एवं अग्रिम कार्रवाई हेत.
- 02. खान नियंत्रक (मध्यांचल), भारतीय खान ब्यूरो, नागपुर
- 03. जिलाधीश, जिला कटनी (म.प्र.) सूचनार्थ ।

(माधवराव साबरे) वरिष्ठ खनन भूविज्ञानी कृते क्षेत्रीय खान नियंत्रक भारतीय खान ब्यूरो