



भारत सरकार /Government of India  
खान मंत्रालय/Ministry of Mines  
भारतीय खान ब्यूरो /Indian Bureau of Mines  
Office Of Regional Controller of Mines



## Violation Letter Speed Post/Email

दूरभाष: (080) 39505368 / 29720499

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

No. MCDR-MiFLOAu/1/2023-BNG-IBM\_RO\_BNG Mine-code: 27KAR16001 Dated: 08/10/2024

To,  
Sri. M. Prakash,  
Executive Director (I/C),  
M/s The Hutti Gold Mines Co. Ltd.,  
Hutti Camp, Hutti  
Taluka-Lingasugur,  
Dist.- Raichur-584115.  
Karnataka  
E m a i l - [prakash.bahadur@ka.gov.in](mailto:prakash.bahadur@ka.gov.in), [rohgm1@gmail.com](mailto:rohgm1@gmail.com), [ghosh.arunava@ka.gov.in](mailto:ghosh.arunava@ka.gov.in),  
[solankar2019@gmail.com](mailto:solankar2019@gmail.com)

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Hutti Gold Mine, ML 2671 over an extent of 528.35 ha, in Hutti Village, Lingasugur Taluk , Raichur District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 27.09.2024 by the undersigned in presence of Shri Arunava Ghosh, Mine Agent, Dr. Sanjeev Kumar Solankar, Geologist, Sri Somesh K V, Mining Engineer and other mine officials:

Rules	Nature of Violations observed
11 (1)	<p>The Review and updation of mining plan was approved by IBM vide letter no. 279/356/92/BNG dated 28/03/2023 for the period 2023-24 to 2027-28 &amp; the Modification to the approved Mining Plan was approved by IBM vide letter no MCDR-MPC0Au/1/2023-BNG-IBM_RO_BNG dated 22/12/2023, for the period 2023-24(1/10/2023 to 31/03/2024) to 2027-28. The deviations observed in mining operation vis-à-vis approved document are given below.</p> <p>i) It is observed during inspection that the statutory clearances from the concerned authority for the enhanced quantity has not been obtained as per the special condition B.4 of the modifications to the approved Mining Plan dated 22/12/2023.</p> <p>ii) It is observed during inspection that against the proposed total off lode development of 3120 metres, only 1131 metres of actual off lode development has been carried out for the year 2023-24. The corresponding actual waste generation is only 42,699 tons~14,233 Cum. against the proposed quantity of 1,43,926 tons~47,975 Cum. Also, against the proposed total on lode development of 5484 metres, only 2690 metres of actual on lode development has been carried out for the year 2023-24.</p> <p>iii) It is observed from the submitted drone data and inspection that at active tailing dump(D-3), 10 metres stage/lift and angle for individual stage have not</p>

	<p>been maintained systematically at PMCP Section-1 from 502 to 512 mRL (N-1792255, E-675374) as per 2023-24 dumping proposal. Also, it is observed from the drone data that vertical extent of active Tailing dump D-3 at PMCP Section -1 has reached 517 mRL which is beyond the proposed maximum limit of 512 mRL for the year 2023-24.</p> <p>iv) It is observed during inspection that the construction of 244.5 metres garland drain as proposed at western portion of active tailing dump D-3, for the year 2023-24 has not been constructed.</p> <p>v) For the year 2023-24 a total plantation of 5000 nos. of plants at 2 ha is proposed at northern portion of inactive tailing dump D-2 along the green belt safety zone. It is observed from submitted 2023-24 drone data &amp; inspection that the plantation has not been carried at the earmarked location as per the proposal.</p>
<b>33</b>	<p>It is observed during inspection that the details of 15 Surface exploratory boreholes and 5 underground exploratory boreholes total amounting to 4491 metres drilled during the year 2023-24 have not been updated in the Geological plan &amp; sections, and submitted to this office as per the provision of this rule.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(Sandeep Kumar Singh)  
Senior Assistant Controller of Mines  
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.
3. Smt. Shilpa R, KAS, The Managing Director, The Hutti Gold Mines Co. Ltd., 3rd Floor, KHB shopping Complex, National Games Village, Koramangla, Bangalore-560 047.

(Sandeep Kumar Singh)  
Senior Assistant Controller of Mines  
Indian Bureau of Mines