



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय /
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या, येशवंतपुर, बेंगलुरु
29, Industrial Suburb, II Stage,
Tumkur Road, Goruguntapalya,
Yeshwantpur, Bangalore – 560022

सं/No.: MCDR-MiFLOFE/12/2023-BNG-IBM_RO_BNG

Minecode: 30KAR03101

सेवा में/ To,

Sri Shantesh Gureddi

Nominated Owner,

Sri Kumarswamy Mineral Exports Pvt. Ltd.,

No. 462, 14th ward, SMIORE Colony, Near Fire Station,
Sandur, Ballari District – 583110

Email: gureddi.shantesh@gmail.com; riom@skmepl.co

विषय/Subject : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Ramanadurga Iron Ore Mine (ML No. 2141) over an area of 59.36 Ha located in Ramanadurga Range (Yeshwanthnagar village) Sandur Taluk, Ballari District, Karnataka state.

महोदय/Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 01/10/2024 by undersigned in presence of Shri Sitarama Kemmannu, General Manager, Shri Nishanth Bhanudas Natiye, Mines Manager, Shri Imran Khan, Geologist and other Mine officials

Rule	Nature of Violations Observed
11(1)	The Mining operations are required to be carried out in accordance with the approved Modifications to the approved Mining Plan document vide letter no. 279/97/89/ BNG dated 11/07/2023. However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows: i. It was proposed to maintain a bench configuration with a maximum height of 7.5m and a minimum width of 10m. However, during the inspection, it was observed that the proposed bench width on the top three benches between section lines J-J' and K-K' is not maintained as per the proposal.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

प्रतिलिपि सूचनार्थ' / Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist