

Showcasue Notice
By Speed Post

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय /
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या, येशवंतपुर, बेंगलुरु

29, Industrial Suburb, II Stage,

Tumkur Road, Goruguntapalya,

Yeshwantpur, Bangalore – 560022

सं/No.: MCDR-MiFLOMgs/2/2022-BNG-IBM_RO_BNG

सेवा में/ To,

Shri N Rajashekhar, Lessee,

No. 38, Sri Nanjundeswara Nilaya,

Udayaravi Road, KHB Colony,

Kuvempunagar, Mysuru-570023

E-mail id- ashokgskumar@gmail.com, rajashekar_mys@yahoo.com

विषय/Subject : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Taloor Magnesite Mine** (ML-2484) (Mine Code-39KAR14013) over an area of 11.88 ha in Mysore district of Karnataka State

महोदय/Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 11.10.2024 by Shri A K Pany, AME and Shri Ashish Kumar Behera, AMG of this office, in presence of Shri Ashok Kumar G.S, Mines Manager and other Mine officials.

Rule s	Nature of Violations Observed
45(7)	In the Annual Return submitted for the year 2023-24, following discrepancies were observed:- (i) In Sl. No. 1(i) of PART-V , the information on exploration i.e. no. of holes at the beginning of the year and cumulative is furnished as '0' (zero). The same is not tally with information as per annual submitted for the year 2022-23 as well as with the mining plan. (ii) In Sl. No. 2 of PART-V , the information on reserve/resource at the beginning of the year and balance as on 31.03.2024 is not tally with reserve/resource figure of last approved mining plan after depleting production achieved. (iii) In Sl. No. 4 of PART-V , the information on OB and waste at the beginning of the year and at the end of year is furnished as '0' (zero). The same is not correct as it is observed that two nos. of waste dumps

	<p>are present within the lease area.</p> <p>(iv) In Sl. No. 3(ii) of PART-VI, the Ex-mine price is not tallying with sale value furnished in Sl No.5 - sale dispatch section.</p> <p>(v) In PART-VII, the mining cost is furnished as Rs. 3854/-. The same is 2.5 times more than the cost of mining estimated, in the feasibility report of mining plan approved on 18.02.2021.</p>
--	---

02. The mining operations and dispatches may be suspended and any action under sub-rule (7) of Rule 45 of MCDR 2017 read with MCDR (Amendment), 2021 may be initiated.
03. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021.
04. You are therefore directed to show cause within a period of **thirty (30) days** from the date of issue of this notice, as to why action under sub-rule (7) of Rule 45 of and Rule 62 of MCDR (Amendment), 2021 shall not be taken against you.
05. You are advised to rectify the above violations immediately and intimate the position to this office **within 30 (thirty) days** from the date of issue of this notice.

भवदीय/Yours faithfully,
Signed by Sudhakara T L
Date: 22-10-2024 14:50:36

(डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.)
वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

प्रतिलिपि सूचनार्थ' / Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.